

8/10/83

# ANNUAL SURVEYS.

43068  
WEDNESDAY 10 OCT 1883

No. \_\_\_\_\_ Survey held at London Date, first Survey 22 Sept Last Survey 6 Oct 1883  
 (Received at London Office, \_\_\_\_\_)  
 No. in Reg. Book. on the SS Pembroke Castle Master Harrison  
 (No. of Visits \_\_\_\_\_)  
 Tonnage { Net 2560 Built at Barrow When built 1883  
 Gross 3536 Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Under Dk. 3639 By whom built Barrow S B Co Owners S Lunn & Co  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Green St Society's Freeboard (if assigned) as painted on Ship \_\_\_\_\_  
 (State Name of Dock.)

Last Survey, No. 3672 Port of Wharfe Classed 100A 2.83  
 (Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_)  
 Present Condition of the  
 Decks good Treennails Reeds good  
 Waterways 11 Breasthooks and Stenson 11  
 Comings 4 Transoms, Pointers, and Crutches 11  
 Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11  
 Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11  
 Planksheers 11 Keelsons 11  
 Sheerstrakes 11 Clamps and Shelves 4  
 Topsides 11 Ceiling 11  
 Wales 11 Rudder 11  
 Plank (Bottom) and Counter 11 Copper or Y.M. brass When put on new  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches 11  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

*Bottom cracked  
 She is now in an efficient state  
 and eligible to remain as classed.*

*Seahouse Martineau*

TUESDAY 23 OCT 1883

Committee's Minute \_\_\_\_\_  
 Character assigned JW 100A


Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 (No. of Visits \_\_\_\_\_)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship \_\_\_\_\_  
 (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 (Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_)  
 Present Condition of the  
 Decks \_\_\_\_\_ Treennails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stenson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_



(If a Steam Ship, state if a Report is also sent on the Machinery...)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)

0520-149N07

No. in the Book	Survey held at	Date, first survey	Classed	Port of	Last Survey, %	General Description, Opinion as to Class, &c.
100	By whom built	When built	By whom built	When built	By whom built	When built
101	By whom built	When built	By whom built	When built	By whom built	When built
102	By whom built	When built	By whom built	When built	By whom built	When built
103	By whom built	When built	By whom built	When built	By whom built	When built
104	By whom built	When built	By whom built	When built	By whom built	When built
105	By whom built	When built	By whom built	When built	By whom built	When built
106	By whom built	When built	By whom built	When built	By whom built	When built
107	By whom built	When built	By whom built	When built	By whom built	When built
108	By whom built	When built	By whom built	When built	By whom built	When built
109	By whom built	When built	By whom built	When built	By whom built	When built
110	By whom built	When built	By whom built	When built	By whom built	When built

No. in the Book	Survey held at	Date, first survey	Classed	Port of	Last Survey, %	General Description, Opinion as to Class, &c.
111	By whom built	When built	By whom built	When built	By whom built	When built
112	By whom built	When built	By whom built	When built	By whom built	When built
113	By whom built	When built	By whom built	When built	By whom built	When built
114	By whom built	When built	By whom built	When built	By whom built	When built
115	By whom built	When built	By whom built	When built	By whom built	When built
116	By whom built	When built	By whom built	When built	By whom built	When built
117	By whom built	When built	By whom built	When built	By whom built	When built
118	By whom built	When built	By whom built	When built	By whom built	When built
119	By whom built	When built	By whom built	When built	By whom built	When built
120	By whom built	When built	By whom built	When built	By whom built	When built