43131

ANNUAL SURVEYS.

THURSDAY 1 NOV 1883

(Received at London Office,)

No. _____ Survey held at London Date, first Survey 23rd Oct. Last Survey 30th Oct. 1883

(No. of Visits ____)

No. in Reg. Book. 732 on the Steel Scw. "British King." Master J. Kelly

Tonnage { Net 2278 Gross 3559 Under Dk. 3255 } Built at Belfast By whom built Harland & Wolff When built Year. 1881 Month. 1st Owners British Ship Owners Co. (Lim.)

Port belonging to Liverpool Destined Voyage New Zealand.

If Surveyed Afloat or in Dry Dock (State Name of Dock.) Royal Albert Dry Dock Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. 42600 Port of Lon. Classed

Years assigned.	Character in Register Book.
	100 A. 1. 6.83.

(Insert Character precisely as in Register Book.)

Present Condition of the

Decks	good	~~Treenails~~	Rivets — good	Windlass and Capstan	good
Waterways	Do.	Breasthooks and Stemson	Do.	Pumps	Do.
Comings	Do.	Transoms, ~~Pointers~~, and Crutches	Do.	Boats	Do.
Upper Deck Beams & Fastenings	Do.	~~Timbers of~~ the Frames at the Openings	Do.	Masts, Yards, &c.	Do.
Lower Deck Beams & Fastenings	Do.	~~Ditto ditto at other places~~		Condition, how ascertained	from the deck
Planksheers	Do.	Keelsons	Do.	Sails	good
Sheerstrakes	Do.	~~Clamps and Shelfs~~		Anchors, No. of	4 B. 1 S. 2 K.
Topsides	Do.	Ceiling	Do.	Cables	complete.
Wales	Do.	Rudder	Do.	Hawsers and Warps	good
~~Plank~~ Keating (Bottom) and Counter	Do.	~~Copper or Y.M.~~ ~~When put on~~		Standing and Running Rigging	Do.
		Caulking of Bottom, Deck, & Waterways	good		

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good.

General Observations, Opinion as to Class, &c. The bottom has been examined & is in good condition. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 9 NOV 1883

Character assigned 100 A

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 ____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 ____

(No. of Visits ____)

No. in Reg. Book. on the _____ Master _____

Tonnage { Net _____ Gross _____ Under Dk. _____ } Built at _____ By whom built _____ When built Year. _____ Month. _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock (State Name of Dock.) _____ Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. _____ Port of _____ Classed

Years assigned.	Character in Register Book.

(Insert Character precisely as in Register Book.)

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelfs		Anchors, No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper or Y.M. When put on		Standing and Running Rigging	
		Caulking of Bottom, Deck, & Waterways			

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 ____

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Form No. 3. Survey, when here ... 18/83.) (If a Steam Ship state if a Tonnage also on the Machinery.)

© 2021 Lloyd's Register Foundation

LON671-0318