

ANNUAL SURVEYS.

43.134
TUESDAY 6 NOV 1883

(Received at London Office,)

No. 335 Survey held at London Date, first Survey 30th Oct^r Last Survey 30th October 1883
No. in Reg. Book. on the Wood Barque Peterborough Master Scoble
Tonnage { Net 561 Built at Sunderland When built 1859 Month. 8
Gross 561
Under Dk. 361 By whom built Austin & Mills Owners J. Hankey & Co.
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Nelson Dry Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 40611 Port of Lon Classed 15 Years assigned. 15 Character in Register Book. A.1.
Present Condition of the
Decks Good Treenails Good cont. Lon. June 75-10
Waterways " Breasthooks and Stemson " H.T. Lon. 78 6,81
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. on felt When put on 6,81
Engine Room Skylights " Caulking of Bottom, Deck, & Waterways Good
Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. "

This vessel has been in dry dock. The metal sheathing patched in a few places and topsides recaulked. The vessel appears in a fit and efficient condition and is in my opinion eligible to remain as classed
Committee's Minute FRIDAY 9 NOV 1883
Character assigned Good 10A Surveyor to Lloyd's Register of British and Foreign Shipping. Henry Hand.
Certificate (if required, to be sent as per margin) " Paid 18

No. 4000-18,583 Survey held at " Date, first Survey " Last Survey " 18"
No. in Reg. Book. on the " Master "
Tonnage { Net " Built at " When built "
Gross "
Under Dk. " By whom built " Owners "
Port belonging to " Destined Voyage "
If Surveyed Afloat or in Dry Dock " Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)
Last Survey, No. " Port of " Classed " Years assigned. " Character in Register Book. "
Present Condition of the
Decks " Treenails "
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. " When put on "
Engine Room Skylights " Caulking of Bottom, Deck, & Waterways "
Coal Bunkers, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways " Hatches "
General Observations, Opinion as to Class, &c. "

Committee's Minute "
Character assigned "
Surveyor to Lloyd's Register of British and Foreign Shipping. "
Certificate (if required, to be sent as per margin) " Paid 18

