

ANNUAL SURVEYS.

43143

(Received at London Office) SATURDAY 10 NOV 1883

No. 449 Survey held at London Date, first Survey 23/10/83 Last Survey 9 Nov 1883
 No. in Reg. Book. on the Iron Ship "Duke of Connaught" Master J. Houston
 Tonnage { Net 999 Built at Glasgow When built 1859 9
 { Gross 1034
 { Under Dk. 954 By whom built A. Stephen & Son Owners Montgomerie & Trockman
 Port belonging to Glasgow Destined Voyage Vancouver's Island
 If Surveyed Afloat or in Dry Dock Nelson dry dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 3532 Port of Wharfedale Years assigned. 7.82 Character in Register Book. A.1.
 Present Condition of the Decks Good rivets Good S.S. Cl. No. 3-80
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats 4 in No
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained from the deck
 Topsides " Ceiling " Sails 2 suits Good
 Wales " Rudder " Anchors, No. of 3B-15-2K
 Plank (Bottom) and Counter " Copper or Y.M. When put on " Cables where seen Good
 Caulking of Bottom, Deck, & Waterways " Hawsers and Warps complete
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good


General Observations, Opinion as to Class, &c.
This vessel has been in dry dock, the bottom re-painted, the pintles to rudder re-riveted, the main topmast renewed. The vessel appears in a fit and efficient condition, and is in my opinion eligible to remain as classed.

Committee's Minute _____
 Character assigned JRM 13 NOV 1883
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____
 { Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. _____ Port of _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Planksheers _____ Keelsons _____ Masts, Yards, &c. _____
 Sheerstrakes _____ Clamps and Shelves _____ Condition, how ascertained _____
 Topsides _____ Ceiling _____ Sails _____
 Wales _____ Rudder _____ Anchors, No. of _____
 Plank (Bottom) and Counter _____ Copper or Y.M. When put on _____ Cables _____
 Caulking of Bottom, Deck, & Waterways _____ Hawsers and Warps _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18



Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.) (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.) (Insert Character precisely as in Register Book.)

LOND 71-0331