


ANNUAL SURVEYS.

43157
FRIDAY 9 NOV 1883

No. 669 Survey held at London Date, first Survey October 18th Last Survey November 1883
(No. of Visits 1)
No. in Reg. Book. on the Iron S. S. "Lord of the Isles" Master J. C. Kelgate
Tonnage { Net 1586 Built at Glasgow When built 1870 6
Gross 2484
Under Dk. 2440 By whom built R. Napier & Sons Owners Shaw Bushby
Port belonging to London Destined Voyage China & Japan
If Surveyed Afloat or in Dry Dock West India Dry Dock & Afloat
(State Name of Dock.)
Last Survey, No. 454 Port of N. Yk Classed 100 A 1
Present Condition of the Decks Good Freemile Rivets Good S.S. Lw N°3-82 9.83
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shells Stringers "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1870
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock the bottom examined and recoated with paint, outside straps fitted on lower joint of rudder plating, butts in the bottom cleaned out and stopped with Cement where necessary, 2 butts of plating in bottom on each side. Now in way of outward Cargo to have outside straps fitted on vessels returns as promised by the Owner. She is in good and efficient Condition eligible to remain at classed.
Committee's Minute FRIDAY 17 NOV 1883 18
Character assigned DRW 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
No. in Reg. Book. on the Master
Tonnage { Net Built at When built Year. Month.
Gross
Under Dk. By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)
Last Survey, No. Port of Classed
Present Condition of the Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shells
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.
Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register
Foundation

LON 671-0345