

43183-

No. 1
No. in Reg. Book. 838
Survey held at London
Date, first Survey October 25th
Last Survey October 31st 1883
on the Steel S. S. Lydian Monarch Master Huggott
(No. of Visits)
Tonnage { Net 2546
Gross 3916
Under Dk. 2855
Built at Dumbarton
When built 1881 5-
By whom built A. McMillan & Sons Owners Royal Exchange Ass. Co.
Port belonging to London
Destined Voyage New York
If Surveyed Afloat or in Dry Dock Millwall Dry Dock & App. Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42188 Port of LONDON

Classed	100 A1
---------	--------

Present Condition of the		Classed	
Decks	Good	Transoms	Good
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or P.M. Cemented When put on	1884
Engine Room Skylights	Good	Caulking of	Good
Coal Bunkers, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good
General Observations. Opinion as to Class &c.		Scuppers	Good
		Cargo and Main Hatchways	Good
		Hatches	Good
		Load Line 23 ft 6 in	1.83
		Shelter 9K	
		Windlass and Capstan	Good
		Pumps	"
		Boats	"
		Masts, Yards, &c.	"
		Condition, how ascertained	by observation
		Sails	Sufficient
		Anchors, No. of	3 B / 1 S & 2 K
		Cables	300 fathoms
		Hawsers and Warps	Sufficient
		Standing and Running Rigging	"

General Observations, Opinion as to Class, &c.

This vessel has now been placed in Dry Dock, the bottom examined and recoated with Paint, the butt & seams in the hull deck examined and recaulked where found necessary, is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

Character assigned

FRIDAY 23 NOV 1833

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid 18

No. _____ *Survey held at* _____ *Date, first Survey* _____ *Last Survey* _____ 18

No. in (No. of Visits _____)

Reg. Book. on the _____ Master

				Year.	Month.
Tonnage	{	Net	Built at	When built	
		Gross			
		Under Dk.	By whom built	Owners	

<i>Port belonging to</i>	<i>Destined Voyage</i>
--------------------------	------------------------

If Surveyed Afloat or in Dry Dock _____ *Society's Freeboard (if assigned) as painted on Ship* _____
(State Name of Dock.)

Last Survey, No. _____ *Port of* _____ *Classed* _____

Present Condition of the			

Decks _____ || *Treenails* _____ || _____

<i>Waterways</i> _____	<i>Breasthooks and Stemson</i> _____	_____
------------------------	--------------------------------------	-------

Comings _____ Transoms, Pointers, and Crutches _____ Windows and Capstan _____

Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats

Lower Deck Beams & Fastenings	Ditto	ditto	at other places	Masts, Yards, &c.

<i>Planksheers</i>	<i>Clamms and Shells</i>	<i>Condition, how ascertained</i>
--------------------	--------------------------	-----------------------------------

Sheerstrakes _____ *Ceiling* _____ *Sails* _____

<i>Topsides</i>	<i>Rudder</i>	<i>Anchors, No. of</i>
-----------------	---------------	------------------------

Wales

Plank (Bottom) and Counter *Caulking of* *Bottom, Deck, & Waterways* *Standing and Running Rigging*

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c. _____

Committee's Minute

Character assigned

Certificate (if required, to be sent as per margin) _____ *Paid* 18