

ANNUAL SURVEYS.

43228
FRIDAY 30 NOV 1883

No. 1232 Survey held at London Date, first Survey Nov 26 Last Survey Nov 26 1883
 No. in Reg. Book. 1232 on the Crown Steamer Austin FRANK Master Houston
 Tonnage 1314 Net 839 Built at Sunderland When built 1868-8
1286 Gross Under Dk. By whom built Laing Owners E Pembroke
 Port belonging to London Destined Voyage Sebastapool & Cardiff
 If Surveyed Afloat or in Dry Dock Lincoln R. Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 28598 Port of Liv Liv Classed 75 A.1.
 Present Condition of the Decks Good Treenails Good Breasthooks and Stenson Good
 Waterways Good Transoms, Pointers, and Crutches Good Windlass and Capstan Good
 Comings Good Timbers of the Frame at the Openings Good Pumps Good
 Upper Deck Beams & Fastenings Good Ditto ditto at other places Good Boats Good
 Lower Deck Beams & Fastenings Good Keelsons Good Masts, Yards, &c. Good
 Planksheers Good Clamps and Shelves Good Condition, how ascertained from deck
 Sheerstrakes Good Ceiling Good Sails will found
 Topsides Good Rudder Good Anchors, No. of 3 B-18-2K
 Wales Good Copper or Y.M. — When put on — Cables what seen good
 Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good Hawsers and Warps sufficient
 Standing and Running Rigging Good

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, the bottom examined, scraped and painted. The vessel now appears in a sound and efficient condition eligible in my opinion to remain as classed.

Committee's Minute _____
 Character assigned TRM 75 A.1 Edward John Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. _____ on the _____ Master _____
 Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Destined Voyage _____
 Port belonging to _____ Society's Freeboard (if assigned) as painted on Ship _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.) _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____
 Caulking of Bottom, Deck, & Waterways _____
 Standing and Running Rigging _____

Committee's Minute _____
 Character assigned _____
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

