

ANNUAL SURVEYS.

43245

(Received at London Office, **WEDNESDAY 11 DEC 1883**)

No. **270** Survey held at **London** Date, first Survey **Dec 4** Last Survey **Dec 6** 18 **83**
 No. in Reg. Book. on the **Iron Sailing Barge SARAH EMMA** Master **H. Lewis**
270 Net **1097** Built at **Liverpool** When built **1860-9**
 Tonnage Gross **1097** Under Dk. **1825** By whom built **J. Vernon Hou** Owners **Hughes & Co**
 Port belonging to **Liverpool** Destined Voyage **Cape RN via Newport**
 If Surveyed Afloat or in Dry Dock **Union Dry Dock** Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.)

Last Survey, No. **27834** Port of **Liv** **Liv** Classed **#A.1**

Present Condition of the Decks **Good** Treenails **Pivots what seen Good** S. S. No. 3. **73** 11-81
 Waterways **4** Breasthooks and Stemson **4** 88 **Liv** **102-81**
 Comings **4** Transoms, Pointers, and Crutches **4** Windlass and Capstan **Good**
 Upper Deck Beams & Fastenings **4** Timbers of the Frame at the Openings **4** Pumps **2 Main 2 Pile**
 Lower Deck Beams & Fastenings **4** Ditto ditto at other places **4** Boats **4**
 Planksheers **4** Keelsons **4** Masts, Yards, &c. **4**
 Sheerstrakes **4** Clamps and Shelves **4** Condition, how ascertained **from deck**
 Topsides **4** Ceiling **4** Sails **well found**
 Wales **4** Rudder **bushed** Anchors, No. of **3 D-18-2 R**
 Plank (Bottom) and Counter **4** Copper or Y.M. When put on **—** Cables **what seen good**
 Engine Room Skylights **—** Coal Bunkers, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **4**
 General Observations, Opinion as to Class, &c. **This vessel has been placed in dry dock the bottom scraped and painted also topsides and a large proportion of timbers lifted & examined she now appears in a sound and efficient condition eligible in my opinion to remain as classed.**

Committee's Minute **FRIDAY 14 DEC 1883**
 Character assigned **J. M. Lawrence & Co. Surveyors to Lloyd's Register of British and Foreign Shipping.**
 Certificate (if required, to be sent as per margin) Paid **18**

No. **—** Survey held at **—** Date, first Survey **—** Last Survey **—** 18
 No. in Reg. Book. on the **—** Master **—**
 Tonnage Net **—** Built at **—** When built **—**
 Gross **—** By whom built **—** Owners **—**
 Under Dk. **—**
 Port belonging to **—** Destined Voyage **—**
 If Surveyed Afloat or in Dry Dock **—** Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.)

Last Survey, No. **—** Port of **—** Classed **—**

Present Condition of the Decks **—** Treenails **—** Windlass and Capstan **—**
 Waterways **—** Breasthooks and Stemson **—** Pumps **—**
 Comings **—** Transoms, Pointers, and Crutches **—** Boats **—**
 Upper Deck Beams & Fastenings **—** Timbers of the Frame at the Openings **—** Masts, Yards, &c. **—**
 Lower Deck Beams & Fastenings **—** Ditto ditto at other places **—** Condition, how ascertained **—**
 Planksheers **—** Keelsons **—** Sails **—**
 Sheerstrakes **—** Clamps and Shelves **—** Anchors, No. of **—**
 Topsides **—** Ceiling **—** Cables **—**
 Wales **—** Rudder **—** Hawseers and Warps **—**
 Plank (Bottom) and Counter **—** Copper or Y.M. When put on **—** Standing and Running Rigging **—**
 Engine Room Skylights **—** Coal Bunkers, Openings, Lids, &c. **—** Scuppers **—** Cargo and Main Hatchways **—** Hatches **—**
 General Observations, Opinion as to Class, &c. **—**

Committee's Minute **—**
 Character assigned **—**
 Certificate (if required, to be sent as per margin) Paid **18**