

8/12/83

ANNUAL SURVEYS.

43284

(Received at London Office, THURSDAY 11 DEC 1883.)


No. 454 Survey held at London Date, first Survey 27 Nov Last Survey 27 Nov 1883
No. in Reg. Book. on the SS Seine Master Manning
Tonnage Net 2200 Built at London When built 1859
Gross 3579 By whom built James SB Co Owners Telegraph Co. & Marine Co.
Under Dk. 2600 Port belonging to London Destined Voyage Telegraph Service
If Surveyed Afloat or in Dry Dock James SN by M Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42297 Port of London
Present Condition of the
Decks good Treenails Rivets good
Waterways q Breasthooks and Stemson 11
Comings 11 Transoms, Pointers, and Crutches 11
Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11
Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11
Planksheers 11 Keelsons q
Sheerstrakes 11 Clamps and Shelves 11
Topsides 11 Ceiling 11
Wales 11 Rudder 11
Plank (Bottom) and Counter 11 Copper or Y.M. bottom When put on now
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches 11
General Observations, Opinion as to Class, &c. Bottom to water
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute
Character assigned THURSDAY 27 DEC 1883
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 4000 Survey held at London Date, first Survey 18 Last Survey 18
No. in Reg. Book. on the SS Seine Master Manning
Tonnage Net 2200 Built at London When built 1859
Gross 3579 By whom built James SB Co Owners Telegraph Co. & Marine Co.
Under Dk. 2600 Port belonging to London Destined Voyage Telegraph Service
If Surveyed Afloat or in Dry Dock James SN by M Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)
Last Survey, No. 42297 Port of London Classed SS London M 3-73. SS London M 2-83.
Present Condition of the
Decks good Treenails Rivets good
Waterways q Breasthooks and Stemson 11
Comings 11 Transoms, Pointers, and Crutches 11
Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11
Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11
Planksheers 11 Keelsons q
Sheerstrakes 11 Clamps and Shelves 11
Topsides 11 Ceiling 11
Wales 11 Rudder 11
Plank (Bottom) and Counter 11 Copper or Y.M. bottom When put on now
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches 11
General Observations, Opinion as to Class, &c. Bottom to water
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute
Character assigned THURSDAY 27 DEC 1883
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



ANNUAL SURVEYS

Annals

No.	Survey held at	Date, first survey	Last Survey	Classed	Part of	Remarks
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50



© 2021
Lloyd's Register
Foundation