

ANNUAL SURVEYS.

43332

THURSDAY 10 JAN 1884

No. 430 Survey held at London Date, first Survey 12 Dec Last Survey 31 Dec 1883
No. in Reg. Book. on the SS Glenlyon Master J. G. G. G.
Tonnage { Net 1373 Built at Glasgow When built 1872 10
Gross 2118 By whom built Sen & Glas Owners M. Gregor & Co
Under Dk. 2083 Port belonging to Glasgow Destined Voyage China
If Surveyed Afloat or in Dry Dock Greens St Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42577 Port of London

Classed 100A-6.83
SS Glen M 2.81

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Revised</u>	<u>Good</u>
Waterways	<u>11</u>	Breasthooks and Stemson	<u>11</u>	
Comings	<u>11</u>	Transoms, Pointers, and Crutches	<u>11</u>	
Upper Deck Beams & Fastenings	<u>11</u>	Timbers of the Frame at the Openings	<u>11</u>	
Lower Deck Beams & Fastenings	<u>11</u>	Ditto ditto at other places	<u>11</u>	
Planksheers	<u>11</u>	Keelsons	<u>11</u>	
Sheerstrakes	<u>11</u>	Clamps and Shelves	<u>11</u>	
Topsides	<u>11</u>	Ceiling	<u>11</u>	
Wales	<u>11</u>	Rudder	<u>11</u>	
Plank (Bottom) and Counter	<u>11</u>	Copper or Y.M. <u>Coated</u> When put on <u>now</u>		
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>Good</u>	
		Hatches	<u>Good</u>	

Bottom & coated.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute

FRIDAY 11 JAN 1884

Character assigned

BS 12.83

100A-1

T. W. Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) 7 Paid 16.1 1884
7.7.8

No. 430 Survey held at London Date, first Survey 12 Dec Last Survey 31 Dec 1883
No. in Reg. Book. on the SS Glenlyon Master J. G. G. G.
Tonnage { Net 1373 Built at Glasgow When built 1872 10
Gross 2118 By whom built Sen & Glas Owners M. Gregor & Co
Under Dk. 2083 Port belonging to Glasgow Destined Voyage China
If Surveyed Afloat or in Dry Dock Greens St Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 42577 Port of London

Classed


Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Revised</u>	<u>Good</u>
Waterways	<u>11</u>	Breasthooks and Stemson	<u>11</u>	
Comings	<u>11</u>	Transoms, Pointers, and Crutches	<u>11</u>	
Upper Deck Beams & Fastenings	<u>11</u>	Timbers of the Frame at the Openings	<u>11</u>	
Lower Deck Beams & Fastenings	<u>11</u>	Ditto ditto at other places	<u>11</u>	
Planksheers	<u>11</u>	Keelsons	<u>11</u>	
Sheerstrakes	<u>11</u>	Clamps and Shelves	<u>11</u>	
Topsides	<u>11</u>	Ceiling	<u>11</u>	
Wales	<u>11</u>	Rudder	<u>11</u>	
Plank (Bottom) and Counter	<u>11</u>	Copper or Y.M. <u>Coated</u> When put on <u>now</u>		
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>Good</u>	
		Hatches	<u>Good</u>	

Committee's Minute

Character assigned

Certificate (if required, to be sent as per margin) 7 Paid 16.1 1884
7.7.8



© 2021

Lloyd's Register
Surveyor to Lloyd's Register of British and Foreign Shipping.
Foundation

Henry

Lloyd's Register
Foundation