

ANNUAL SURVEYS.

43371

(Received at London Office)

THURSDAY 10 JAN 1884

No. 293 Survey held at London Date, first Survey 13 Dec Last Survey 24 Dec 1883

No. in Reg. Book. on the SS Florida Master Joyce (No. of Visits)

Tonnage { Net 2044 Built at Newcastle When built 1882 Year. 9 Month.

Gross 3138 By whom built C Mitchell & Co Owners Nelson Sonkin & Co

Under Dk. 2524 Port belonging to London Destined Voyage New Zealand

If Surveyed Afloat or in Dry Dock Blackwall Dock Society's Freeboard (if assigned) as painted on Ship

(State Name of Dock.)

Last Survey, No. 42809 Port of London Classed 100A-4.83

Present Condition of the Decks Good MOULDED DEPTH of Ship, if not yet recorded in Register Book Good

Waterways 4 Treenails Rivets after removal Good

Comings 4 Breasthooks and Stemson 4

Upper Deck Beams & Fastenings 4 Transoms, Pointers, and Crutches 4

Lower Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4

Planksheers 4 Ditto ditto at other places 4

Sheerstrakes 4 Keelsons 4

Topsides 4 Clamps and Shelves 4

Wales 4 Ceiling 4

Plank (Bottom) and Counter 4 Rudder 4

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches 4

General Observations, Opinion as to Class, &c. Bottom & Coasting

She is now in an efficient state and eligible to remain as classed.

Senhouse Martin & Co

Committee's Minute TRW TUESDAY 22 JAN 1884

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master (No. of Visits)

Tonnage { Net Built at When built Year. Month.

Gross By whom built Owners

Under Dk. Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

(State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book

Waterways Treenails

Comings Breasthooks and Stemson

Upper Deck Beams & Fastenings Transoms, Pointers, and Crutches

Lower Deck Beams & Fastenings Timbers of the Frame at the Openings

Planksheers Ditto ditto at other places

Sheerstrakes Keelsons

Topsides Clamps and Shelves

Wales Ceiling

Plank (Bottom) and Counter Rudder

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

If required, to be sent as per margin

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

Florida



© 2021

Lloyd's Register
Foundation