

ANNUAL SURVEYS.

43393

No. 411 Survey held at London Date, first Survey 17 Jan Last Survey 17 Jan 1884
(Received at London Office, TUESDAY 22 JAN 1884)
No. in Reg. Book. on the BK Wolseley Master H Attervool
(No. of Visits)
Tonnage Net 340 Built at Greenock When built 1876 Month. 9
Gross 353 By whom built J E Scott Owners Bullard & King
Under Dk. 307
Port belonging to London Destined Voyage not known
If Surveyed Afloat or in Dry Dock Off Fountain BK Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 41893 Port of Lon Classed 100 A 10.82
Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book
found Treenails found
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. When put on "
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers found Cargo and Main Hatchways found Hatches "
General Observations, Opinion as to Class, &c.

She is now in an efficient state and eligible to remain as classed.

Leithhouse Martindale

Committee's Minute FRIDAY 25 JAN 1884
Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 411 Survey held at London Date, first Survey 17 Jan Last Survey 17 Jan 1884
(Received at London Office, TUESDAY 22 JAN 1884)
No. in Reg. Book. on the BK Wolseley Master H Attervool
(No. of Visits)
Tonnage Net 340 Built at Greenock When built 1876 Month. 9
Gross 353 By whom built J E Scott Owners Bullard & King
Under Dk. 307
Port belonging to London Destined Voyage not known
If Surveyed Afloat or in Dry Dock Off Fountain BK Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 41893 Port of Lon Classed 100 A 10.82
Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book
found Treenails found
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. When put on "
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers found Cargo and Main Hatchways found Hatches "
General Observations, Opinion as to Class, &c.

Committee's Minute
Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

LON672-0026