

ANNUAL SURVEYS.

43423

TU-SDAY 8 JAN 1884

No. 701 Survey held at London Date, first Survey 19 Dec Last Survey 31 Dec 1883
No. in Reg. Book. on the Iron Screw Steamer "ETHEL" Master Binder
Tonnage 166 Net 281 Gross 246 Under Dk. 246 Built at Belfast When built 1880
By whom built Workman & Clark Owners J. Danks
Port belonging to not fixed Destined Voyage not fixed
If Surveyed Afloat or in Dry Dock Fleethers St. Society's Freeboard (if assigned) is painted on Ship
(State Name of Dock.)

Last Survey, No. 28332 Port of Iron Bel. Classed 90 A 1
10.80

Present Condition of the
Decks Good

Waterways ✓

Comings ✓

Upper Deck Beams & Fastenings ✓

Lower Deck Beams & Fastenings ✓

Planksheers ✓

Sheerstrakes ✓

Topsides ✓

Wales ✓

Plank (Bottom) and Counter ✓

Treenails Quits where seen Good

Breasthooks and Stemson ✓

Transoms, Pointers, and Crutches ✓

Timbers of the Frame at the Openings ✓

Ditto ditto at other places ✓

Keelsons ✓

Clamps and Shelves ✓

Ceiling ✓

Rudder ✓

Copper or Y.M. — When put on —

Caulking of
Bottom, Deck, & Waterways good

Windlass and Capstan Good

Pumps ✓

Boats 2 ✓

Masts, Yards, &c. ✓

Condition, how ascertained from deck

Sails good

Anchors, No. of 2 B 1 S 1 K

Cables scated complete

Hawsers and Warps sufficient

Standing and Running Rigging good

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.

This vessel has placed in dry dock bottom examined scraped & painted new propeller fitted to replace one broken. Repairs to cathead & anchor fittings. It should be noted that the Tonnage has been recalculated by the Board of Trade, and consequently the Register book is incorrect. She now appears in a sound & efficient condition in my opinion eligible to remain as classed.

Character assigned TRM 90 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) — Paid 18

No. — Survey held at — Date, first Survey — Last Survey — 18—

No. in Reg. Book. on the —

Master —

(No. of Visits —)

Year. —

Month. —

Tonnage —

Net —

Built at —

When built —

Gross —

Under Dk. —

By whom built —

Owners —

Port belonging to —

Destined Voyage —

If Surveyed Afloat or in Dry Dock —

Society's Freeboard (if assigned) as painted on Ship —

(State Name of Dock.)

Last Survey, No. —

Port of —

Classed —

Present Condition of the
Decks —

Waterways —

Comings —

Upper Deck Beams & Fastenings —

Lower Deck Beams & Fastenings —

Planksheers —

Sheerstrakes —

Topsides —

Wales —

Plank (Bottom) and Counter —

Treenails —

Breasthooks and Stemson —

Transoms, Pointers, and Crutches —

Timbers of the Frame at the Openings —

Ditto ditto at other places —

Keelsons —

Clamps and Shelves —

Ceiling —

Rudder —

Copper or Y.M. — When put on —

Caulking of
Bottom, Deck, & Waterways —

Windlass and Capstan —

Pumps —

Boats —

Masts, Yards, &c. —

Condition, how ascertained —

Sails —

Anchors, No. of —

Cables —

Hawsers and Warps —

Standing and Running Rigging —

Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. —

Scuppers —

Cargo and Main Hatchways —

Hatches —

General Observations, Opinion as to Class, &c. —

Committee's Minute —

Character assigned —

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) — Paid 18

LON672-0057