

# ANNUAL SURVEYS.

43430

No. 1088 Survey held at London Date, first Survey 19 Jan'y Last Survey 22<sup>d</sup> Jan'y 1884  
 No. in Reg. Book. on the SS Bengella Master W. Edmund  
 Tonnage { Net 1041 Built at Sunderland When built 1881 Month. 12  
 Gross 1557  
 Under Dk. 1567 By whom built W. Edmund & Co Owners Bullard & Co  
 Port belonging to London Destined Voyage Port Natal  
 If Surveyed Afloat or in Dry Dock Bridgway St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42501 Port of Low

Classed 1000 5.83

Present Condition of the

MOULDED DEPTH of Ship, if not yet recorded in Register Book		Character in Register Book.	
Decks	Treenails	Years assigned.	
Waterways	Breasthooks and Stemson		
Comings	Transoms, Pointers, and Crutches		
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings		
Lower Deck Beams & Fastenings	Ditto ditto at other places		
Planksheers	Keelsons		
Sheerstrakes	Clamps and Shelves		
Topsides	Ceiling		
Wales	Rudder		
Plank (Bottom) and Counter	Copper or Y.M. <u>Copper</u> When put on <u>now</u>		
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways		
Coal Bunkers, Openings, Lids, &c.	Scuppers		
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways		
	Hatches		

*She is now in an efficient state and eligible as classed.*

*Leahurst Martindale*

Committee's Minute TUESDAY 5 FEB 1884

Character assigned 1000A

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 1088 Survey held at London Date, first Survey 19 Jan'y Last Survey 22<sup>d</sup> Jan'y 1884

No. in Reg. Book. on the SS Bengella Master W. Edmund  
 Tonnage { Net 1041 Built at Sunderland When built 1881 Month. 12  
 Gross 1557  
 Under Dk. 1567 By whom built W. Edmund & Co Owners Bullard & Co  
 Port belonging to London Destined Voyage Port Natal  
 If Surveyed Afloat or in Dry Dock Bridgway St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42501 Port of Low

Classed 1000 5.83

Present Condition of the

MOULDED DEPTH of Ship, if not yet recorded in Register Book		Character in Register Book.	
Decks	Treenails	Years assigned.	
Waterways	Breasthooks and Stemson		
Comings	Transoms, Pointers, and Crutches		
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings		
Lower Deck Beams & Fastenings	Ditto ditto at other places		
Planksheers	Keelsons		
Sheerstrakes	Clamps and Shelves		
Topsides	Ceiling		
Wales	Rudder		
Plank (Bottom) and Counter	Copper or Y.M. <u>Copper</u> When put on <u>now</u>		
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways		
Coal Bunkers, Openings, Lids, &c.	Scuppers		
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways		
	Hatches		

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

LON 672-0065



