

# ANNUAL SURVEYS.

43446

7 FEB 1884

(Received at London Office)

No. 221 Survey held at London Date, first Survey 31 Jan Last Survey 1 Feb 18 84  
 No. in Reg. Book. on the SS Relaw Master Suntar  
 Tonnage 593 Built at Sunderland When built 1865 Month. 10  
 Gross 793 By whom built J Loring Owners Commercial S. Ship Co  
 Under Dk. 694 Port belonging to London Destined Voyage Collier  
 If Surveyed Afloat or in Dry Dock Budg by BK Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42817 Port of Lon

Classed 95A1 8.83

Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book  
 Waterways good Breasthooks and Stemson good  
 Comings good Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Lower Deck Beams & Fastenings good Ditto ditto at other places good  
 Planksheers good Keelsons good  
 Sheerstrakes good Clamps and Shelves good  
 Topsides good Ceiling good  
 Wales good Rudder good  
 Plank (Bottom) and Counter good Copper or Y.M. Coated When put on new  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom be coated

She is now in an efficient state and eligible to remain as classed.

Committee's Minute

FRIDAY 8 FEB 1884

Character assigned

B.S. 1.84

95A1

J. M. Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) 5 Paid 20 Feb 1884

No.        Survey held at        Date, first Survey        Last Survey        18         
 No. in Reg. Book. on the        Master         
 Tonnage        Built at        When built        Year.        Month.         
 Gross        By whom built        Owners         
 Under Dk.        Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock        Society's Freeboard (if assigned) as painted on Ship

Last Survey, No.        Port of       

Classed       

Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book  
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M.        When put on         
 Caulking of Bottom, Deck, & Waterways         
 Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
 General Observations, Opinion as to Class, &c.       

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)        Paid        18       

LON672-0079

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/84.)  
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)



Polaw

