

ANNUAL SURVEYS.

43500

(Received at London 21 FEB 1884)

No. 291 Survey held at London Date, first Survey 31 Jan Last Survey 16 Feb 1884
No. in Reg. Book. on the John Duthie Master Same
Tonnage { Net 1031 Built at Aberdeen When built 1864 10
Gross 1031
Under Dk. 918 By whom built Duthie Owners J Duthie
Port belonging to Aberdeen Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Horseferry by SA Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 41512 Port of LonClassed 12 A 5.82

Present Condition of the

Decks	<u>good</u>	MOULDED DEPTH of Ship, if not yet recorded in Register Book	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	<u>"</u>	Treenails	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Condition, how ascertained	<u>from SK</u>
Planksheers	<u>"</u>	Ditto ditto at other places	<u>"</u>	Sails	<u>good</u>
Sheerstrakes	<u>"</u>	Keelsons	<u>"</u>	Anchors, No. of <u>3 No. SK & Kedge</u>	
Topsides	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables <u>Part on SK</u>	<u>good</u>
Wales	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Rudder	<u>"</u>	Standing and Running Rigging	<u>"</u>
Engine Room Skylights	<u>"</u>	Copper or Y.M. <u>Y Metal</u> When put on <u>5.82</u>			
Coal Bunkers, Openings, Lids, &c.	<u>"</u>	Caulking of <u>Patched now</u>			
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	<u>good</u>		
		Scuppers	<u>good</u>		
		Cargo and Main Hatchways	<u>good</u>		
		Hatches	<u>"</u>		

Yellow Metal patched.
She is now in an efficient state and
eligible to remain as classed.

Lost Boiler Anchor now replaced
29-3-14 Tested to 28-10-2-14 River Wear Machine dated 13th Sept 1883
Signed J Hartnup.

Committee's Minute

FRIDAY 22 FEB 1884

Character assigned

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 291 Survey held at London Date, first Survey 31 Jan Last Survey 16 Feb 1884

No. in Reg. Book. on the John Duthie Master Same
Tonnage { Net 1031 Built at Aberdeen When built 1864 10
Gross 1031
Under Dk. 918 By whom built Duthie Owners J Duthie

Port belonging to Aberdeen Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Horseferry by SA Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 41512 Port of LonClassed 12 A 5.82

Present Condition of the


Decks	<u>good</u>	MOULDED DEPTH of Ship, if not yet recorded in Register Book	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	<u>"</u>	Treenails	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Condition, how ascertained	<u>from SK</u>
Planksheers	<u>"</u>	Ditto ditto at other places	<u>"</u>	Sails	<u>good</u>
Sheerstrakes	<u>"</u>	Keelsons	<u>"</u>	Anchors, No. of <u>3 No. SK & Kedge</u>	
Topsides	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables <u>Part on SK</u>	<u>good</u>
Wales	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Rudder	<u>"</u>	Standing and Running Rigging	<u>"</u>
Engine Room Skylights	<u>"</u>	Copper or Y.M. <u>Y Metal</u> When put on <u>5.82</u>			
Coal Bunkers, Openings, Lids, &c.	<u>"</u>	Caulking of <u>Patched now</u>			
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	<u>good</u>		
		Scuppers	<u>good</u>		
		Cargo and Main Hatchways	<u>good</u>		
		Hatches	<u>"</u>		

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register
Foundation

LON 672-0143

No.	Survey held at	Date, first Survey	Master	When built	By whom built	Port of	Last Survey, No.	Present Condition of the	Remarks
1									
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									
46									
47									
48									
49									
50									
51									
52									
53									
54									
55									
56									
57									
58									
59									
60									
61									
62									
63									
64									
65									
66									
67									
68									
69									
70									
71									
72									
73									
74									
75									
76									
77									
78									
79									
80									
81									
82									
83									
84									
85									
86									
87									
88									
89									
90									
91									
92									
93									
94									
95									
96									
97									
98									
99									
100									

