

ANNUAL SURVEYS.

43516

SATURDAY 23 FEB 1884

No. 71 Survey held at London Date, first Survey 9th Feb Last Survey 22nd Feb 1884
 No. in Reg. Book. on the Iron S. "Panmure" Master Hughes
 Tonnage 1505 Net Built at Glasgow When built 1875 Month 6th
1581 Gross Under Dk. 1396 By whom built A. Stephen & Sons Owners D. Bruce & Co.
 Port belonging to Dundee Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock In Poplar Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42474 Port of Lon Classed 100A.1.
 Present Condition of the Decks good MOULDED DEPTH of Ship, if not yet recorded in Register Book 5,83
 Waterways D^o Breasthooks and Stemson good
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves D^o
 Topsides D^o Ceiling D^o
 Rudder D^o
 Copper or Y.M. D^o When put on D^o
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights D^o Coal Bunkers, Openings, Lids, &c. D^o Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. The upper deck recaulked.
Vessel surveyed with part outward cargo in hold amidships.
She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 28 FEB 1884 Surveyor to Lloyd's Register of British and Foreign Shipping. J. A. Truscott.
 Character assigned 100A.1 Certificate (if required, to be sent as per margin) Paid 18

No. 71 Survey held at London Date, first Survey 9th Feb Last Survey 22nd Feb 1884
 No. in Reg. Book. on the Iron S. "Panmure" Master Hughes
 Tonnage 1505 Net Built at Glasgow When built 1875 Month 6th
1581 Gross Under Dk. 1396 By whom built A. Stephen & Sons Owners D. Bruce & Co.
 Port belonging to Dundee Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock In Poplar Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42474 Port of Lon Classed 100A.1.
 Present Condition of the Decks good MOULDED DEPTH of Ship, if not yet recorded in Register Book 5,83
 Waterways D^o Breasthooks and Stemson good
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves D^o
 Topsides D^o Ceiling D^o
 Rudder D^o
 Copper or Y.M. D^o When put on D^o
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights D^o Coal Bunkers, Openings, Lids, &c. D^o Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. The upper deck recaulked.
Vessel surveyed with part outward cargo in hold amidships.
She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 28 FEB 1884 Surveyor to Lloyd's Register of British and Foreign Shipping. J. A. Truscott.
 Character assigned 100A.1 Certificate (if required, to be sent as per margin) Paid 18

If a steam ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

