

ANNUAL SURVEYS.

43547

FRIDAY 22 FEB 1884

(Received at London)

No. 478 Survey held at London Date, first Survey 29th Feb Last Survey 1884
No. in Reg. Book. on the Iron BR. 'Mahabad' Master McAllum
(No. of Visits 9)
Tonnage { Net 1143 Built at Liverpool When built 1864
Gross 1191 By whom built Other & Co Owners J. Stephens & Sons
Under Dk. 1092
Port belonging to London Destined Voyage Cardiff thence Hong Kong
If Surveyed Afloat or in Dry Dock Blackwall Pt. St Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 28454 Port of LiverpoolClassed S.S. 3-82 Character in Register Book. *A-1Years assigned. 1/1882Present Condition of the Decks GoodMOULDED DEPTH of Ship, if not yet recorded in Register Book GoodWaterways do.Breasthooks and Stemson do.Comings do.Transoms, Pointers, and Crutches do.Upper Deck Beams & Fastenings do.Timbers of the Frame at the Openings do.Lower Deck Beams & Fastenings do.Ditto ditto at other places do.Plank sheers do.Keelsons do.Sheerstrakes do.Clamps and Shelves do.Topsides do.Ceiling do.Wales do.Rudder do.Plank (Bottom) and Counter GoodCopper or Y.M. do. When put on do.Engine Room Skylights do.Caulking of Bottom, Deck, & Waterways GoodCoal Bunkers, Openings, Lids, &c. do.Scuppers do.General Observations, Opinion as to Class, &c. do.Cargo and Main Hatchways do.Deck house has now been substantiallybuilt up. before main hatch, about 13ft x 31ft.This vessel appears in good efficient condition & capablein our opinion to remain as classed.

Committee's Minute

FRIDAY 7 MARCH 1884

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 478 Survey held at London Date, first Survey 29th Feb Last Survey 1884No. in Reg. Book. on the Iron BR. 'Mahabad' Master McAllum(No. of Visits 9)Tonnage { Net 1143 Built at Liverpool When built 1864Gross 1191 By whom built Other & Co Owners J. Stephens & SonsUnder Dk. 1092Port belonging to London Destined Voyage Cardiff thence Hong KongIf Surveyed Afloat or in Dry Dock Blackwall Pt. St Society's Freeboard (if assigned) as painted on Ship

(State Name of Dock.)

Last Survey, No. 28454 Port of LiverpoolClassed S.S. 3-82 Character in Register Book. *A-1Years assigned. 1/1882Present Condition of the Decks GoodMOULDED DEPTH of Ship, if not yet recorded in Register Book GoodWaterways do.Breasthooks and Stemson do.Comings do.Transoms, Pointers, and Crutches do.Upper Deck Beams & Fastenings do.Timbers of the Frame at the Openings do.Lower Deck Beams & Fastenings do.Ditto ditto at other places do.Plank sheers do.Keelsons do.Sheerstrakes do.Clamps and Shelves do.Topsides do.Ceiling do.Wales do.Rudder do.Plank (Bottom) and Counter GoodCopper or Y.M. do. When put on do.Engine Room Skylights do.Caulking of Bottom, Deck, & Waterways GoodCoal Bunkers, Openings, Lids, &c. do.Scuppers do.Cargo and Main Hatchways do.Hatches do.General Observations, Opinion as to Class, &c. do.

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON672-0191