

Report of Survey for Repairs of Engines and Boilers.

No. 357 (Received at London Office, FRIDAY 7 MARCH 1884)
 No. in Survey held at London Date, first Survey Last Survey 188
 Reg. Book. 357 on the Machinery of the S.S. "Duminda" (Number of Visits)

Tonnage, Gross 2977 Built at Dumbarton When built 1875
 Ditto, Net 1943 Owners D. Macneil + J. Denny Port belonging to Glasgow
 Diameter of Cylinder 47 1/2 Engines made by Denny & Co When made 1875
 Length of Stroke 48" Boilers made by D. When made 1875
 Pressure of Steam 65 If Surveyed Afloat or in Dry Dock Years assigned 100 A 1
 Registered Horse Power 400 (State name of Dock.) Character in Register Book. 100 A 1
 Last Survey No. Port L.M.B. 1079.B.S. 12.82.

Particulars of Repairs and Examination of Machinery Boilers in accordance with the Rules for S.S. No. 2
 Examined cylinders, slides, all pumps & crank shafts and found them good; Propeller and sea connections examined found good
 Boilers and Safety valves examined & found in fair condition


General Observations, Opinion, and Recommendation:— The machinery of this vessel is now in good order and safe working condition and eligible in my opinion to have the notification L.M.B. 2.84 Subject to the resurvey of boilers as per Rule

Entry or Registering Fee... £
 Survey Fee (per Section 28) 17 1/4 £ 3 : 3 : 0 received by me, David Purves
 Certificate (if required) ... £ 5- { 29/3 1884 } 478
 to be sent as per margin.

Committee's Minute TUESDAY 11 MARCH 1884 188

Assigned L.M.B. 2.84

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

LON672-0197