

ANNUAL SURVEYS.

43575

(Received at London Office, TUESDAY 12 FEB 1884)

No. 362 Survey held at London Date, first Survey 6th Feb Last Survey 9th Feb 1884
 No. in Reg. Book. on the Iron Screw Steamer BERRINGTON Master Garrison
 Tonnage 508 Net Built at Newcastle When built 1865 - 9
294 Gross Under Dk. 224 By whom built Palmer's Coy Owners S. Luwick Esq.
 Port belonging to Sunderland Destined Voyage Shields.
 If Surveyed Afloat or in Dry Dock on Poutoons Society's Freeboard (if assigned) as painted on Ship


Last Survey, No. 42111 Port of Lon. Classed 80 A.1
 Present Condition of the Decks Good MOULDED DEPTH of Ship, if not yet recorded in Register Book
 Waterways do Treenails Revised when seen good
 Comings do Breasthooks and Stemson do
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Planksheers do Ditto ditto at other places do
 Sheerstrakes do Keelsons do
 Topsides do Clamps and Shelves do
 Wales do Ceiling do
 Plank (Bottom) and Counter do Rudder do
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Several frames to bulwark on Port side bent, angle iron rail broken, straightened & repaired, waterway and rail removed in wake hereof. The bottom examined scraped and painted, several rivets in keel replaced, and new stopper to Rudder fitted. The vessel now appears to be in a sound efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 13 MARCH 1884
 Character assigned B.S. 2. 24 Surveyor to Lloyd's Register of British and Foreign Shipping. Edward John Terry
 Certificate (if required, to be sent as per margin) 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Net Built at When built
 Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed
 Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book
 Waterways Treenails
 Comings Breasthooks and Stemson
 Upper Deck Beams & Fastenings Transoms, Pointers, and Crutches
 Lower Deck Beams & Fastenings Timbers of the Frame at the Openings
 Planksheers Ditto ditto at other places
 Sheerstrakes Keelsons
 Topsides Clamps and Shelves
 Wales Ceiling
 Plank (Bottom) and Counter Rudder
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LBN 672-0225

Form No. 3 for Annual Survey, 1884. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

BERRINGTON

No.	Ship	Date	Where	Part of	Last Survey, No.	Present Condition of the	Remarks
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150