

ANNUAL SURVEYS.

43645

WEDNESDAY 26 MARCH 1884

No. 47 Survey held at London Date, first Survey 1884 Last Survey 2nd March 1884
 No. in Reg. Book. on the Iron Screw Steamer GARTH CASTLE Master Bunce
 Tonnage 2381 Built at Glasgow When built 1880 12
3705 By whom built J. Elder & Co Owners J. Currie & Co
3537 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Gruis tupper St Society's Freeboard (if assigned) as painted on Ship —

Last Survey, No. 43196 Port of Lon Classed 100.A-1
 Present Condition of the Decks Good
 Waterways 4 Breasthooks and Stemson Good
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shelves Stringers 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. This vessel was placed in dry dock, the bottom cleaned and painted, she now appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 1 APRIL 1884
 Character assigned 100A-1
 Edward Jno Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) — Paid 18

No. — Survey held at — Date, first Survey — Last Survey — 18—
 No. in Reg. Book. on the — Master —
 Tonnage — Built at — When built — —
— By whom built — Owners —
 Port belonging to — Destined Voyage —
 If Surveyed Afloat or in Dry Dock — Society's Freeboard (if assigned) as painted on Ship —

Last Survey, No. — Port of — Classed —
 Present Condition of the Decks —
 Waterways — Breasthooks and Stemson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways —
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches —
 General Observations, Opinion as to Class, &c. —

Committee's Minute —
 Character assigned —
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) — Paid 18

Garth Castle



© 2021

Lloyd's Register
Foundation