

# ANNUAL SURVEYS.

43649

(Received at London Office) MONDAY 31 MARCH 1884

No. 93 Survey held at London Date, first Survey 23<sup>rd</sup> Nov<sup>r</sup> Last Survey 19<sup>th</sup> March 1883  
No. in Reg. Book. on the Ketch "Active." Master G. Steele  
Tonnage { Net 40 Built at Jersey When built 1864 10<sup>th</sup> Month.  
Gross 45 By whom built J. H. Picot. Owners R. J. Chambers & Co.  
Under Dk. 44  
Port belonging to Jersey Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Afloat at Toppings Wharf Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.) Also at Kings Wharf  
Last Survey, No. 1922 Port of Jersey Classed 8 Years assigned. A.1  
Present Condition of the Decks good Rest. Jer. Dec. 80- 6 2, 82

Treenails good  
Breasthooks and Stenson good  
Transoms, Pointers, and Crutches good  
Timbers of the Frame at the Openings good  
Ditto ditto at other places good  
Keelsons good  
Clamps and Shelves good  
Ceiling good  
Rudder good  
Copper or Y.M. When put on  
Caulking of Bottom, Deck, & Waterways good

Windlass and Capstan good  
Pumps good  
Boats good  
Masts, Yards, &c. good  
Condition, how ascertained from the deck  
Sails good  
Anchors, No. of 2 B. 1 K.  
Cables complete  
Hawsers and Warps good  
Standing and Running Rigging good

Scuppers good Cargo and Main Hatchways good Hatches good

The fore boom renewed. As this vessel is marked "salted" in the Register Book, on be cased in & salted for 5<sup>th</sup> vessels' length at each end. The top only of the keelson is salted. On the 20<sup>th</sup> March/84 I wrote to the Owners recommending that the sides of keelson at ends be salted and desired to be informed when the same would be done - but have received no reply. In other respects the vessel is in good and efficient condition & eligible to remain as classed.

Committee's Minute

TUESDAY 1 APRIL 1884

Character assigned

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_

No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Under Dk. \_\_\_\_\_

Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship  
(State Name of Dock.) \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_

Present Condition of the Decks \_\_\_\_\_  
Waterways \_\_\_\_\_  
Comings \_\_\_\_\_  
Upper Deck Beams & Fastenings \_\_\_\_\_  
Lower Deck Beams & Fastenings \_\_\_\_\_  
Planksheers \_\_\_\_\_  
Sheerstrakes \_\_\_\_\_  
Topsides \_\_\_\_\_  
Wales \_\_\_\_\_  
Plank (Bottom) and Counter \_\_\_\_\_  
Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON 672-0311