

ANNUAL SURVEYS.

43696
THURSDAY 17 APRIL 1884

No. 86 Survey held London Date, first Survey 7 April Last Survey 10 April 1884
No. in Reg. Book. on the Iron S "SERAPIS" Master Gray
Tonnage { Net 995 Built at Greenock When built 1876 - 11
Gross 1027 By whom built E. Scott. Owners W Lund
Under Dk. 933 Port belonging to London Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock Greenock Society's Freeboard (if assigned) as painted on Ship 4-9
(State Name of Dock.)

Last Survey, No. 16997 Port of Low. Lon Classed 100 A. 1.
Present Condition of the Good Treonails Rivets Good
Decks Good Breasthooks and Stenson Good
Waterways 4 Transoms, Pointers, and Crutches 4
Comings 4 Timbers of the Frame at the Openings 4
Upper Deck Beams & Fastenings 4 Ditto ditto at other places 4
Lower Deck Beams & Fastenings 4 Keelsons 4
Planksheers 4 Clamps and Shells Strangers 4
Sheerstrakes 4 Ceiling 4
Topsides 4 Rudder pietles bushed 4
Wales 4 Copper or Y.M. — When put on —
Plank (Bottom) and Counter 4 Caulking of —
Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed
The bottom, has been examined, scraped & coated with paint

Committee's Minute FRIDAY 13 APRIL 1884
Character assigned 100 A. 1.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 77 Survey held at London Date, first Survey 24 March Last Survey 26 March 1884
No. in Reg. Book. on the Iron S "VANGUARD" Master Shaw
Tonnage { Net 688 Built at Port Glasgow When built 1832
Gross 688 By whom built — Owners J Boncompagni & Co
Under Dk. 688 Port belonging to Liverpool Destined Voyage Brisbane
If Surveyed Afloat or in Dry Dock Blackwall Point Society's Freeboard (if assigned) as painted on Ship —
(State Name of Dock.)

Last Survey, No. 28597 Port of Liv. Classed SS. Liv 103-83
Present Condition of the Good Treonails Rivets Good
Decks Good Breasthooks and Stenson 4
Waterways 4 Transoms, Pointers, and Crutches 4
Comings 4 Timbers of the Frame at the Openings 4
Upper Deck Beams & Fastenings 4 Ditto ditto at other places 4
Lower Deck Beams & Fastenings 4 Keelsons 4
Planksheers 4 Clamps and Shells Strangers 4
Sheerstrakes 4 Ceiling 4
Topsides 4 Rudder pietles bushed 4
Wales 4 Copper or Y.M. — When put on —
Plank (Bottom) and Counter 4 Caulking of —
Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
This vessel now appears to be in a sound & efficient condition eligible in my opinion to remain as classed

Committee's Minute FRIDAY 13 APRIL 1884
Character assigned 100 A. 1.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

LON672-0365

*Serapis
Tanguard*

[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page. The text appears to be organized into columns and rows, possibly a ledger or a list of entries.]



© 2021

Lloyd's Register
Foundation