

ANNUAL SURVEYS.

43805

TUESDAY 20 MAY 1884

No. 30 Survey held at London Date, first Survey 21 April Last Survey 9th May 1884
No. in Reg. Book. on the BK Balcombe Master
Tonnage Net 360 Built at Sunderland When built 1861 - 7
Gross 360 By whom built Austin Owners Swankey & Co
Under Dk. 360

Port belonging to Nelson By SW Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock (State Name of Dock.) Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41927 Port of Son Classed 12A/11.82
Present Condition of the MOULDED DEPTH of Ship, if not yet recorded in Register Book 18-6 1/2
Decks Treenails 18-6 1/2

Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. Metal When put on 11.82
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c. Owing to damage, one new Roughtie Standish, part new Channel boards & rails & part new Bulwark on both sides and part refastened including Japfullant Bulwark & Rails, Caulked from top of metal upwards.

She is now in an efficient state and eligible to remain as classed.
Committee's Minute FRIDAY 23 MAY 1884
Character assigned J.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Net Built at When built
Gross By whom built Owners
Under Dk.


Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock (State Name of Dock.) Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed
Present Condition of the MOULDED DEPTH of Ship, if not yet recorded in Register Book
Decks Treenails

Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

© 2021



Lloyd's Register Foundation

LONG 72-0490

Baltimore
Whitney & Parrott



© 2021
Lloyd's Register
Foundation