

ANNUAL SURVEYS.

43828

THURSDAY 15 MAY 1884

No. 741 Survey held at LONDON Date, first Survey 7 May Last Survey 1884  
No. in Reg. Book. on the Crow Sewer & BRITISH QUEEN Master J. Wills  
Net 2247 Built at Belfast When built 1880 - 11  
Tonnage Gross 3558 Under Dk. 3254 By whom built Carland & Co Owners British Ship owners Co. Ltd.  
Port belonging to Liverpool Destined Voyage Wellington  
If Surveyed Afloat or in Dry Dock A dry dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 2009 Port of San Luis Classed 100A-1  
Present Condition of the Decks Good MOULDED DEPTH of Ship, if not yet recorded in Register Book 3.83  
Waterways Good Breasthooks and Stemson Good Windlass and Capstan Good  
Comings Good Transoms, Pointers, and Crutches Good Pumps 6  
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good Boats 7  
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good Masts, Yards, &c. Good  
Planksheers Good Keelsons Good Condition, how ascertained from deck  
Sheerstrakes Good Clamps and Shelves Stringers Sails 2 Suits  
Topsides Good Ceiling Good Anchors, No. of 3 13, 18-2K  
Wales Good Rudder repaired Cables what seen  
Plank (Bottom) and Counter Good Copper or Y.M. When put on Hawers and Warps sufficient  
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c.

This vessel having been placed in dry dock the bottom examined cleaned and coated, she now appears to be in sound and efficient condition eligible in my opinion to remain as classed

Committee's Minute FRIDAY 30 MAY 1884  
Character assigned 100A-1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

No.        Survey held at        Date, first Survey        Last Survey 18  
No. in Reg. Book. on the        Master         
Net        Built at        When built        Year.        Month.         
Tonnage Gross        Under Dk.        By whom built        Owners         
Port belonging to        Destined Voyage         
If Surveyed Afloat or in Dry Dock        Society's Freeboard (if assigned) as painted on Ship

Last Survey, No.        Port of        Classed         
Present Condition of the Decks        MOULDED DEPTH of Ship, if not yet recorded in Register Book         
Waterways        Breasthooks and Stemson        Windlass and Capstan         
Comings        Transoms, Pointers, and Crutches        Pumps         
Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings        Boats         
Lower Deck Beams & Fastenings        Ditto ditto at other places        Masts, Yards, &c.         
Planksheers        Keelsons        Condition, how ascertained         
Sheerstrakes        Clamps and Shelves        Sails         
Topsides        Ceiling        Anchors, No. of         
Wales        Rudder        Cables         
Plank (Bottom) and Counter        Copper or Y.M.        When put on        Hawers and Warps         
Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
General Observations, Opinion as to Class, &c.

Committee's Minute         
Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18