

ANNUAL SURVEYS.

43858

THURSDAY 5 JUNE 1884,

No. 549 Survey held at London Date, first Survey April 30th Last Survey May 12th 1884
No. in Reg. Book. on the Brig "Mary Letter" Master J. Roberts
Net 188 Built at Milford When built 1864 — 8 Month.
Tonnage { Gross 188 By whom built Lewis Owners Roberts & Griffiths
Under Deck 185
Port belonging to Barnardston Destined Voyage
If Surveyed Afloat or in Dry Dock West India Docks Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 402 Port of New York

Classed

Years assigned. 12Character in Register Book. A 1

Present Condition of the

Decks

MODELLER

DEPTH of Ship if not yet recorded in Register Book

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. on felt

When put on

Caulking of

Bottom, Deck, & Waterways

Cost Paid Aug 76H. T. L. 81

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

FRIDAY 6 JUNE 1884

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

No. 236 Survey held at London Date, first Survey May 2nd Last Survey May 20th 1884
No. in Reg. Book. on the Screw Schooner "Diana" Master J. Allan
Net 104 Built at Glasgow When built 1869 — 3 Month.
Tonnage { Gross 179 By whom built Stephen Owners Hudson's Bay Co.
Under Deck 179
Port belonging to London Destined Voyage Labrador
If Surveyed Afloat or in Dry Dock Leamhouse Dry Dock & Wharf Society's Freeboard (if assigned) as painted on Ship
pt. d. 69 C.F. (State Name of Dock.)

Last Survey, No. 42477 Port of London

Classed

Years assigned. 18Character in Register Book. A 1

Present Condition of the

Decks

MODELLER

DEPTH of Ship if not yet recorded in Register Book

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

S.S. Cl. 81

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

The caulking in the bottom examined and attended to where found necessary, and the general equipment attended to, the vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

FRIDAY 6 JUNE 1884

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

LON672-0550