

# ANNUAL SURVEYS.

43882

FRIDAY 30 MAY 1884

No. 682 Survey held at London Date, first Survey April 24 Last Survey 1884  
 No. in Reg. Book. on the Iron S.S. "Lorne" Master J. R. Read  
 Tonnage 763 Built at Hull When built 1873 - 3  
68684 Under Dk. 918 By whom built Gilbert & Cooper Owners W. Bailey  
 Port belonging to Hull Destined Voyage Copenhagen & Coningsby  
 If Surveyed Afloat or in Dry Dock Repents Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5471 Port of Hull Classed 90A1  
 Present Condition of the Decks good MOULDED DEPTH of Ship, if not yet recorded in Register Book 3.84  
 Waterways good Treenails Keels when seen good  
 Comings good Breasthooks and Stemson good  
 Upper Deck Beams & Fastenings good Transoms, Pointers, and Crutches good  
 Lower Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Plank sheers good Ditto ditto at other places not seen  
 Sheerstrakes good Keelsons when seen good  
 Topsides good Clamps and Shelves Stringers  
 Wales good Ceiling good  
 Plank (Bottom) and Counter good Rudder good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock the bottom examined and recoated with black varnish - the propeller taken off and a new one with four blades fitted, she is now in good and efficient condition and eligible in my opinion to remain as classed.


Committee's Minute TUESDAY 10 JUNE 1884  
 Character assigned JRM 90A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.          Survey held at          Date, first Survey          Last Survey          18  
 No. in Reg. Book. on the          Master           
 Tonnage          Built at          When built           
         Under Dk.          By whom built          Owners           
 Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock          Society's Freeboard (if assigned) as painted on Ship

Last Survey, No.          Port of          Classed           
 Present Condition of the Decks          MOULDED DEPTH of Ship, if not yet recorded in Register Book           
 Waterways          Treenails           
 Comings          Breasthooks and Stemson           
 Upper Deck Beams & Fastenings          Transoms, Pointers, and Crutches           
 Lower Deck Beams & Fastenings          Timbers of the Frame at the Openings           
 Plank sheers          Ditto ditto at other places           
 Sheerstrakes          Keelsons           
 Topsides          Clamps and Shelves           
 Wales          Ceiling           
 Plank (Bottom) and Counter          Rudder           
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches           
 General Observations, Opinion as to Class, &c.         

Committee's Minute           
 Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

© 2021



Lloyd's Register Foundation

LON672-0574

If a Steam Ship, state if a Report is also sent on the Machinery

The Surveyors are requested not to write on or below the space for Committee's Minute

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.