

# ANNUAL SURVEYS.

43954  
TUESDAY 17 JUNE 1894

(Received at London Office,)

No. 293 Survey held at London Date, first Survey \_\_\_\_\_ Last Survey 10/6/84 18  
 No. in Reg. Book. on the 300 Iron S.S. Florida Master Swyer  
(No. of Visits)  
293 2044 Built at Newcastle When built 1882 - 9  
Year. Month.  
 Tonnage 3138 By whom built C Mitchell & Co Owners Nelson Sonkin & Co  
Under Dk.  
2924 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock London Society's Freeboard (if assigned) as painted on Ship \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. 43971 Port of London Classed 100 A.1.  
Years assigned. Character in Register Book.  
 Present Condition of the Decks Good  
 Waterways 4 Treenails Good Breasthooks and Stemson 4  
 Comings 4 Transoms, Pointers, and Crutches 4 Windlass and Capstan Good  
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Pumps 4  
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Boats 4  
 Planksheers 4 Keelsons 4 Masts, Yards, &c. 4  
 Sheerstrakes 4 Clamps and Shelves 4 Condition, how ascertained from deck  
 Topsides 4 Ceiling 4 Sails 1 Suit good  
 Wales 4 Rudder 4 Anchors, No. of 3 B, 1 S, 2 K  
 Plank (Bottom) and Counter 4 Copper or Y.M. — When put on — Cables what seen good  
 Caulking of Bottom, Deck, & Waterways good Hawsers and Warps sufficient  
 Standing and Running Rigging good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. The Bottom cleaned & scraped & coated. Several Ratts stopped, and also several in upper part of rudder and in the keel & stern post renewed. The vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

Committee's Minute \_\_\_\_\_  
 Character assigned TBM 100 A.1  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Edward Jno Tierney  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
(No. of Visits)  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_ Year. Month.  
Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. Character in Register Book.  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_ Treenails \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_ Windlass and Capstan \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_ Pumps \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_ Boats \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_ Masts, Yards, &c. \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_ Condition, how ascertained \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_ Sails \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_ Anchors, No. of \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_ Cables \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_ Hawsers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18



LON672-0666

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/9/83.)  
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)