

ANNUAL SURVEYS.

TUESDAY 1 JULY 1884

(Received at London Office)

No. 402 Survey held at London Date, first Survey ✓ Last Survey 19/6/84 18
(No. of Visits)
 No. in Reg. Book. on the Stat of Roumania Master Callet
Year. Month.
 Tonnage 4163 Built at Glasgow When built 1883 - 3
Net Gross Under Dk.
2657 By whom built D. Elder & Co Owners New Zealand & Co
 Port belonging to Lyttelton NZ Destined Voyage Lyttelton & Dunedin NZ
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 43519 Port of Lon Classed 100A1
Years assigned. Character in Register Book.
 Present Condition of the Decks Good Treenails Good Good
 Waterways 4 Breasthooks and Stenson 4 Windlass and Capstan Good
 Comings 4 Transoms, Pointers, and Crutches 4 Pumps 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Boats 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Masts, Yards, &c. 4
 Planksheers 4 Keelsons 4 Condition, how ascertained from deck
 Sheerstrakes 4 Clamps and Shelves 4 Sails 1 Set good
 Topsides 4 Ceiling 4 Anchors, No. of 3 B, 2 K
 Wales 4 Rudder 4 Cables what seen good
 Plank (Bottom) and Counter 4 Copper or Y.M. — When put on — Hawasers and Warps Sufficient
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The Bottom cleaned and coated
Several defective rivets replaced afloat on Star side. The vessel
now appears to be in a sound and efficient
condition eligible in my opinion to remain as
a classed

Committee's Minute _____
 Character assigned T.M. 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
(No. of Visits)
 No. in Reg. Book. on the _____ Master _____
Year. Month.
 Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Hawasers and Warps _____
 Caulking of Bottom, Deck, & Waterways _____ Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-18/83.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 LONG 73-0046

