

ANNUAL SURVEYS.

44016

(Received at London Office, FRIDAY 13 JULY 1884)

No. Survey held at London Date, first Survey 20th June Last Survey 16th July 1884
 No. in Reg. Book. on the Iron Ship "Canterbury" Master J. M. Millan
 Tonnage 1245 Built at Port Glasgow When built 1874 Month 5th
1308 By whom built R. Duncan & Co Owners Albion Shipping Co (Lim.)
 Under Dk. 1126 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock In Rugg's Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 4274 Port of Low Classed 100A.1.

Present Condition of the Decks good MOULDED DEPTH of Ship, if not yet recorded in Register Book good
 Waterways Do Breasthooks and Stemson Do
 Comings Do Transoms, ~~Pointers~~, and Crutches Do
 Upper Deck Beams & Fastenings Do ~~Timbers of the Frame~~ at the Openings Do
 Lower Deck Beams & Fastenings Do ~~Ditto ditto at other places~~
 Planksheers Do Keelsons Do
 Sheerstrakes Do ~~Clamps and Shelves~~
 Topsides Do Ceiling Do
~~Wales~~ Plating Do Rudder Do
~~Plank~~ (Bottom) and Counter Do ~~Copper or Y.M.~~ When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. The bottom has been examined & crated.
The deck plating in way of house for Refrigerator has been extended four feet and made watertight, to allow for a horizontal boiler being fitted in lieu of vertical one.
This vessel appears in a good and efficient condition and is in our opinion eligible to remain as classed.

Committee's Minute TUESDAY 22 JULY 1884 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 100A.1 Certificate (if required, to be sent as per margin) Paid 18
Henry Dixon

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed

Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.
 Committee's Minute Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned Certificate (if required, to be sent as per margin) Paid 18