

ANNUAL SURVEYS.

MONDAY 14 JULY 1884

44048

(Received at London Office, July 8 1884)

No. 43 Survey held at Louisa Date, first Survey July 8 Last Survey July 12 1884
 No. in Reg. Book. on the Iron S/S Louisa Master Robertson
 Tonnage { Net 2332 Built at Newcastle When built 1873-10
 Gross 3594 By whom built C Mitchell & Co Owners W Milburn & Co
 Under Dk. 353 Port belonging to Louisa Destined Voyage Supposed Egypt
 If Surveyed Afloat or in Dry Dock A. Dry Dk Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 5667 Port of Rpt. Lett Classed 100A1
 Present Condition of the Decks Good Character in Register Book. 3-82

Waterways	4	Breasthook and Stenson	4	Windlass and Capstan	Good
Comings	4	Transoms, Pointers, and Crutches	4	Pumps <u>2</u> <u>down</u> <u>tows</u>	4
Upper Deck Beams & Fastenings	4	Timbers of the Frame at the Openings	4	Boats <u>8</u>	4
Lower Deck Beams & Fastenings	4	Ditto ditto at other places	4	Masts, Yards, &c.	4
Planksheers	4	Keelsons	4	Condition, how ascertained <u>from deck</u>	
Sheerstrakes	4	Clamps and Shelves <u>Stringers</u>	4	Sails <u>2</u> <u>Suits</u> <u>Good</u>	Good
Topsides	4	Ceiling	4	Anchors, No. of <u>4B</u> <u>1S</u> <u>2K</u>	
Wales	4	Rudder	4	Cables <u>what seen</u> <u>Good</u>	Good
Plank (Bottom) and Counter	4	Copper or Y.M. <u>—</u> When put on <u>—</u>		Hawsers and Warps <u>Sufficient</u>	
Engine Room Skylights <u>Good</u>		Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging <u>Good</u>	
Coal Bunkers, Openings, Lids, &c. <u>Good</u>		Scuppers <u>Good</u>		Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>

General Observations, Opinion as to Class, &c.
This vessel has been placed in dry dock the bottom cleaned, scraped and painted she now appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

Committee's Minute _____
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping. Edward W. Turner
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Character in Register Book. _____

Waterways	_____	Breasthooks and Stenson	_____	Windlass and Capstan	_____
Comings	_____	Transoms, Pointers, and Crutches	_____	Pumps	_____
Upper Deck Beams & Fastenings	_____	Timbers of the Frame at the Openings	_____	Boats	_____
Lower Deck Beams & Fastenings	_____	Ditto ditto at other places	_____	Masts, Yards, &c.	_____
Planksheers	_____	Keelsons	_____	Condition, how ascertained	_____
Sheerstrakes	_____	Clamps and Shelves	_____	Sails	_____
Topsides	_____	Ceiling	_____	Anchors, No. of	_____
Wales	_____	Rudder	_____	Cables	_____
Plank (Bottom) and Counter	_____	Copper or Y.M. _____ When put on _____		Hawsers and Warps	_____
Engine Room Skylights _____		Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging	_____
Coal Bunkers, Openings, Lids, &c. _____		Scuppers _____		Cargo and Main Hatchways	Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery)

(Insert Character precisely as in Register Book.)

