

# ANNUAL SURVEYS.

44052

(Received at London Office, TUESDAY 22 JULY 1884)

No. 139 Survey held at London Date, first Survey 17 July Last Survey 18 84  
 No. in Reg. Book. on the Stou Scrub Pathan Master Rowley  
 Tonnage { Net 1762 Built at Glasgow When built 1883 — 3  
 Gross 2709 By whom built Aitken & Mansel Owners Gallaty & Co.  
 Under Dk. 2527 Port belonging to Pocheater Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Eye Albert & Co. Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 43474 Port of Volp Classed 100 A 1.  
 Present Condition of the Decks Good Good Good  
 Waterways ✓ Breasthooks and Stemson ✓ Windlass and Capstan Good  
 Comings ✓ Transoms, Pointers, and Crutches ✓ Pumps ✓  
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓ Boats ✓  
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓ Masts, Yards, &c. ✓  
 Planksheers ✓ Keelsons ✓ Condition, how ascertained from deck  
 Sheerstrakes ✓ Clamps and Shelves Strung Sails 1 Suit  
 Topsides ✓ Ceiling ✓ Anchors, No. of 3 10, 10, 2 10  
 Wales ✓ Rudder ✓ Cables what seen  
 Plank (Bottom) and Counter ✓ Copper or Y.M. — When put on — Hawers and Warps Sufficient  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.  
This vessel has been placed in dry dock the bottom cleaned and coated. She now appears to be in a sound and efficient condition eligible in my opinion to remain as classed

Committee's Minute Edward Jno Tierney  
 Character assigned 100 A 1. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. — Survey held at — Date, first Survey — Last Survey 18  
 No. in Reg. Book. on the — Master —  
 Tonnage { Net — Built at — When built —  
 Gross — By whom built — Owners —  
 Under Dk. — Port belonging to — Destined Voyage —  
 If Surveyed Afloat or in Dry Dock — Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. — Port of — Classed —  
 Present Condition of the Decks — — —  
 Waterways — Breasthooks and Stemson — Windlass and Capstan —  
 Comings — Transoms, Pointers, and Crutches — Pumps —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings — Boats —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places — Masts, Yards, &c. —  
 Planksheers — Keelsons — Condition, how ascertained —  
 Sheerstrakes — Clamps and Shelves — Sails —  
 Topsides — Ceiling — Anchors, No. of —  
 Wales — Rudder — Cables —  
 Plank (Bottom) and Counter — Copper or Y.M. — When put on — Hawers and Warps —  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches —

General Observations, Opinion as to Class, &c.  
 Committee's Minute —  
 Character assigned —  
 Certificate (if required, to be sent as per margin) Paid 18