

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office,

TUESDAY 12 AUGUST 1884

No. 44114
 No. in Survey held at London Date, First Survey Aug 9th Last Survey Aug 11th 1884
 Reg. Book 250 on the Crown S. "Star of Russia" Master Simpson
 TONNAGE under Tonnage Deck 768 Built at Belfast When built 1874 - 12
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1981 Owners J. Corry & Co Port belonging to Belfast
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 1882 By whom built Harland & Wolff Destined Voyage Melbourne
 Engine Room
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock Green's Dock
 (State Name of Dock)

Length of Poop 54 ft. Ditto, Forecastle 41 ft. Ditto, Raised Qr. Deck _____ ft.
 Last Survey, No. 43113 Port Lon Classified 100A/10-83

REPAIRS, OR EXAMINATION AS PER RULE
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage to be separate from Repairs from other causes.)
 Society's Freeboard (if assigned) as painted on Ship } in salt water 5-5
58 Lon 802-83 } in fresh water 5-1
 State dates of any letters respecting this case MOULDED DEPTH of Ship, if not recorded in Register Book 26-0

Annual Survey

This vessel was placed in dry dock the bottom examined cleaned and painted. The timbers cleared &c.

Present Condition of the	Good	Treenails or Rivets	Good	Windlass and Capstan	Good
Decks	✓	Breasthooks and Stenson	✓	Pumps	✓
Waterways	✓	Transoms, Pointers, and Crutches	✓	Boats	✓
Comings	✓	Timbers of the Frame at the openings	✓	Masts, Yards, &c.	✓
Upper Deck Beams & Fastenings	✓	Ditto Ditto at other places	✓	Condition, how ascertained	from deck
Lower Deck Beams & Fastenings	✓	Keelsons	✓	Sails	2 Suits good
Planksheers	✓	Clamps and Shelves	✓	Anchors	No. of 3 B, 1 S, 2 K
Sheerstrakes	✓	Ceiling	✓	Cables	what seen good
Topsides	✓	Rudder	✓	Hawsers and Warps	Sufficient
Wales	✓	Copper (or Y.M.) - When put on	-	Standing & Running Rigging	good
Plank (Bottom) and Counter	✓	Cement (if Iron Ship)	✓	Cargo and Main Hatchways	good
Engine Room Skylights	-	Caulking of Bottom, Deck, & Waterways	✓	Hatches	good
Coal Bunker, Openings, Lids, &c.	-	Scuppers	good		

General Observations, Opinion as to Class, &c.
 The vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed

Entry or Registration Fee ... £ : :
 Survey Fee (per Section 28) ... £ : :
 Special Damage Fee (per Section 28) £ : :
 * Certificate (if required) ... £ : :
 Travelling Expenses (if any) ... £ : :
 Second Surveyor's Fee (if any) ... £ : :
 received by me, }
 188 }

Lawson Pro Surveys
 Surveyor to Lloyd's Register of British and Foreign Shipping.


Committee's Minute
 Character assigned 100A/1

TUESDAY 26 AUGUST 1884



THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Star of Russia



© 2021

Lloyd's Register
Foundation