

Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office, 29/8/84.)  
No. in Reg. Book. Survey held at London. Date, first Survey June 11<sup>th</sup> Last Survey June 13<sup>th</sup> 1884.  
24. on the Machinery of the S. S. "Cadiiz" (Number of Visits 12)  
Tonnage, Gross 1400 Built at Sunderland. When built 1869.  
Ditto, Net 901. Owners J. Hall jr. & Co. Port belonging to London.  
Diameter of Cylinder 34 $\frac{1}{2}$  + 64 Engines made by Blair & Co. When made 1879.  
Length of Stroke 42" Boilers made by Do. When made 1879.  
Pressure of Steam 16 lbs. If Surveyed Afloat or in Dry Dock Regent Dock. (State name of Dock.)  
Registered Horse Power 160. Classified 100A1.  
Last Survey No. \_\_\_\_\_ Port L. M. C. 11. 33.

Particulars of Repairs and Examination In Annual Survey

(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. Tail shaft drawn in examined found to be in good condition, the stern bush relined & propeller refitted.


General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

Entry or Registering Fee... £ : :  
Survey Fee (per Section 28) ... £ : : received by me,  
Certificate (if required) ... £ : : 188  
to be sent as per margin.  
(Travelling Expenses, if any, £ )

Committee's Minute FRIDAY 29 AUGUST 1884 188

Assigned

Geo. E. Milner  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation

LDN673-0187



It is submitted that this vessel is  
eligible to remain as classed

D.S.

27/8/84

\*



© 2021

Lloyd's Register  
Foundation