

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

TUESDAY 10 MARCH 1885

No. 573 in Survey held at London Date, first Survey 9th Feby Last Survey 19 Feby 1885
 Reg. Book. 573 on the Machinery of the S. S. "Shoreham" (Number of Visits 4)
 Tonnage, Gross 491 Built at Port Glasgow When built 1872 8
 Ditto, Net 293 Owners S. Clarke & Co Port belonging to London
 Diameter of Cylinder 24.42 Engines made by Walker Andrsn. & Co When made 1872
 Length of Stroke 30 Boilers made by Walker Andrsn. & Co When made 1879
 Pressure of Steam 60 If Surveyed Afloat or in Dry Dock Carlers & Co Classed 90 A 1
 Registered Horse Power 80 (State Name of Dock.)
 Last Survey No. L.M.C. 2.81. Port Bs 12.82

Particulars of Repairs and Examination Special Survey No 3
 (State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Seacocks & connections & found them good. New lignum vitae has been fitted in the stem tube
 Examined tailshaft funnel shaft & crankshaft & found them good. The tailshaft is a new one.
 Examined the Pumps cylinders & slide valves & found them good.
 Examined the main boiler, steam dome & donkey boiler & found them good.
 Examined the safety valves & found them in good working order.

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel is now in a safe working condition & eligible in my opinion to have the notification L.M.C. 2.85 recorded in the Register Book

Office or Registration Fee (per Sec. 27) £ - : - : -
 Survey Fee (per Section 28) £ 3 : 3 : -
 Special Damage Fee (per Section 28) £ - : - : -
 *Certificate (if required) £ : 2 : 6
 Travelling Expenses (if chargeable) £ - : - : -

received by me,
 14. 3 1885

Committee's Minute TUESDAY 10 MARCH 1885
 Assigned M. 2, 85

C. D. Stromeier
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register Foundation
 LON 674-0321

State of the Hull of the Ship

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel is eligible to have the notification. Lm 6. 2 85 recorded the boilers being subject to resurvey as per Rule.

D.P.

9/3/85

Boat's name

Boat's number

Boat's class

Boat's length

Boat's width

Boat's depth

Boat's draught

Boat's engine

Boat's gear

Boat's rig

Boat's sails

Boat's deck

Boat's hull

Boat's keel

Boat's rudder

Boat's mast

Boat's boom

Boat's spinnaker

Boat's jib

Boat's main

Boat's mizzen

Boat's foremast

Boat's mainmast

Boat's mizzenmast

Boat's rigging

Boat's blocks

Boat's pulleys

Boat's ropes

Boat's lines

Boat's cables

Boat's wires

Boat's bands

Boat's straps

Boat's buckles

Boat's buttons

Boat's rivets

Boat's bolts

Boat's nuts

Boat's washers

Boat's spacers

Boat's sleeves

Boat's collars

Boat's flanges

Boat's gaskets

Boat's seals

Boat's O-rings

Boat's gaskets



LLOYD'S REGISTER FOUNDATION