

REPORT of SURVEY for REPAIRS, &c.

44771

Received in London Office,

WEDNES. 11 MARCH 1885

No. 361 Survey held at London Date, First Survey 2^d Feb Last Survey 9th March 1885
 Reg. Book. 361 on the SS Libra Master _____

TONNAGE:—
 NET 570 Built at Dundee By whom Gourlay Bros When 1869
 GROSS 1084 Owners General Stronach & Co Port belonging to London
 UNDER DK. 831 Owner's Address _____
 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Name of Dock Leppind Dry Dock Destined Voyage not known
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Qr. Deck _____ ft.: Moulded Depth _____ ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 42098 Port Lon
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water _____ ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in fresh water _____ ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE
at present placed in the dry dock the bottom cleaned and coated, the chain cables ranged in the bottom of the dry dock for the Government Surveyors, also examined by me 270 fathoms good, new main & fore topmasts pitch pine.

PRESENT CONDITION OF THE							
Decks	<i>good</i>	<i>Plating</i> Plank (Bottom) & Counter	<i>good</i>	Ceiling	<i>good</i>	Boats	<i>4</i>
Waterways	"	Iron or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	<i>From Str</i>
Up'r Dk. Beams & Fastenings		Transoms, Pointers, & Crutches		Pumps	"	Sails	<i>good</i>
Low'r Dk. Beams & Fastenings		Timbers of Frame at the openings		Cement (if Iron Ship)	"	Anchors	<i>No. of 3 Bbs. & 12 Rops</i>
Planksheers		Ditto ditto at other places		Caulking of Bot'm, D'k, & Watrways	<i>4</i>	Cables	<i>Examined 270 fms good</i>
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)		Hawsers & Warps	"
Topsides	"	Clamps & Shelves		When put on		Standing & Running Rigging	"
Wales	"					Hatches	<i>good</i>
Engine Room Skylights	<i>good</i>	Coal Bunker, Openings, Lids, &c.	<i>good</i>	Scuppers	<i>good</i>	Cargo & Main Hatchways	<i>good</i>

General Observations, Opinion as to Class, &c. :
She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale.

Entry Fee (if chargeable) per Scale I., Sec. 27. £ : :
 Office Fee (if chargeable) per Scale II., Sec. 27. £ : :
 Survey Fee (per Section 28) £ : :
 Special Damage Fee (if any) (per Sec. 28) £ : :
 *Certificate (if required). See margin £ : :
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :

received by me, }
 188

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 24 MARCH 1885

Committee's Minute
 Character assigned

[Handwritten signature]



If a Steam Ship, state whether or not a Report is also sent on the Machinery.

Insert Character precisely as in Register Book.

REPORT OF SURVEY FOR REPAIRS, &c.

Libra

No.	Description of Work	Quantity	Unit	Rate	Amount
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100