

REPORT of SURVEY for REPAIRS, &c.

44907

Received in London Office,

SAT 18 APRIL 1885

Survey held at London Date, First Survey 24 March Last Survey 16th April 1885
(No. of Visits)

on the SS Glenartney Master _____ YEAR. MONTH.

TONNAGE: NET 1400 Built at Glasgow By whom London & Glasgow When 1873 9

GROSS 2143 Owners McGregor, Gow & Co. Port belonging to Glasgow

UNDER DK. 2065 Owner's Address _____
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock _____ Name of Dock Poplar Dry Dock Destined Voyage China

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Classed _____ Years assigned, if a Wood Ship. _____ Character in Register Book. 100 F110 84 SS in M 2.81

Last Survey, No. 44303 Port Lon

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water _____ ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in fresh water _____ ft. ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in the dry dock & the bottom cleaned and coated.

PRESENT CONDITION OF THE								
Decks	<i>good</i>	Plank (Bottom) & Counter	<i>good</i>	Celling	<i>good</i>	Boats	<i>good</i>	
Waterways	"	Trunnels or Rivets	"	Rudder	"	Masts, Yards, &c.	"	
Timings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	<i>from SK</i>	
Upper Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	<i>good</i>	
Lower Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors	No. of <i>8 Bro. 4 1/2 No</i>	
Stanksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	<i>good</i>	
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"	
Upsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"	
Stables	"					Hatches	"	
Engine Room Skylights	<i>good</i>	Coal Bunker, Openings, Lids, &c.	<i>good</i>	Scuppers	<i>good</i>	Cargo & Main Hatchways	<i>good</i>	

General Observations, Opinion as to Class, &c.:


She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	} received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
Certificate (if required). See margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

FRI 1 MAY 1885

Committee's Minute _____
 Character assigned *LDW*



© 2021
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 Lloyd's Register Foundation
 LON674-0520

REPORT OF SURVEY FOR REPAIRS & CO.

Henry

No.	Date	Part	Material	Remarks
18	1888
19	1888
20	1888
21	1888
22	1888
23	1888
24	1888
25	1888
26	1888
27	1888
28	1888
29	1888
30	1888
31	1888
32	1888
33	1888
34	1888
35	1888
36	1888
37	1888
38	1888
39	1888
40	1888
41	1888
42	1888
43	1888
44	1888
45	1888
46	1888
47	1888
48	1888
49	1888
50	1888

Surveyor to Lloyd's Register of British & Foreign Shipping