

REPORT of SURVEY for REPAIRS, &c.

No. 951 Survey held at London Date, First Survey 19th Nov Last Survey 21st Nov 1885

TONNAGE:- NET 1722 1695 GROSS 2664 1963 UNDER DK. 2422

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.

Last Survey, No. 44991 Port Lon

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in the Dry Dock and examined, and the bottom cleaned and coated.

PRESENT CONDITION OF THE					
Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good
Waterways	"	Trunnels or Rivets	"	Rudder	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (If Iron Ship)	"
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M.	"
Topsides	"	Clamps & Shelves	"	(State if on Felt.)	"
Wales	"			When put on	"
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers	Good
				Cargo & Main Hatchways	Good
				Hatches	"

General Observations, Opinion as to Class, &c.:

She is now in an efficient state and eligible to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27. £ : : Office Fee (if chargeable) per Scale II., Sec. 27. £ : : Survey Fee (per Section 28) £ : : Special Damage Fee (if any) (per Sec. 28) £ : : Certificate (if required) to be sent as per margin £ : : Travelling Expenses (if chargeable) £ : : Second Surveyor's Fee (if any) £ : :

Committee's Minute Character assigned

REPORT OF SURVEY FOR REPAIRS TO SHIPS

Alameda

18
Date of Survey
By whom
Name of Ship
Tonnage
Dinner
Remarks

19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

General Observations, Opinion and Recommendation
Remarks

Remarks