

45978

REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

FRIDAY 12 MARCH 1886

No. in Reg. Book. Survey held at *London* Date, First Survey *8th Feb^y* Last Survey *9th March 1886*

660 on the *Iron Scw. Stm. Bk. Lord of the Isles.* Master *J. C. Felgate*

TONNAGE:— NET *1586* Built at *Glasgow* By whom *R. Napier & Sons.* When *1870* MONTH *6th*

GROSS *2484* Owners *Shaw, Bushby & Co* Port belonging to *London.*

UNDER DK. *2440* Owners' Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock & Dry Dock Name of Dock *West India (Dry Dock)* Destined Voyage *Japan.*

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. Character in Register Book.

Last Survey, No. *4592 3 Port* *Lon.* Classified *S.L. Lon. N^o 3-82.* 100 A.1

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE

The bottom has been examined and coated. Rudder pintles renewed. Lower part of rudder plating renewed each side. One boat new. Part cargo in hold when surveyed.