

# REPORT of SURVEY for REPAIRS, &C.

46014  
THURS 1 APRIL 1886

Received in London Office.

No. 46014

No. in Reg. Book. 643 Survey held at London Date, First Survey 27th March Last Survey 30th March 1886  
(No. of Visits Three)

on the Iron screw Steamer "BRACADAILE" Master E. Weddall  
TONNAGE:— NET 1416 GROSS 2198 UNDER DK. 2061  
Built at Newcastle By whom Palmer's Co. When 1881 MONTH 6  
Port belonging to Newcastle

Owner's Address J. Temperley & Co.  
Owner's Address (if not already recorded in Appendix to Register Book.)  
If Surveyed Afloat or in Dry Dock afloat Name of Dock Victoria Destined Voyage Halifax & Boston

Length of Poop \_\_\_\_\_ ft.: of Forecastle \_\_\_\_\_ ft.: of Raised Or. Deck \_\_\_\_\_ ft.: Moulded Depth \_\_\_\_\_ ft. \_\_\_\_\_ ins.  
(if these particulars are not yet recorded in the Register Book.)  
Years assigned, if a Wood Ship. \_\_\_\_\_ Character in Register Book. 100 A1  
Classed \_\_\_\_\_

Last Survey, No. L5946 Port London  
Society's Freeboard (if assigned) \_\_\_\_\_ in salt water \_\_\_\_\_ ft. \_\_\_\_\_ ins.  
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case. \_\_\_\_\_ as painted on Ship \_\_\_\_\_ in fresh water \_\_\_\_\_ ft. \_\_\_\_\_ ins.

REPAIRS, OR EXAMINATION AS PER RULE Freeboard

*This vessel has been examined afloat in the Victoria Dock, and the freeboard assigned by the Committee viz. 4'-11 1/2" in winter, 4'-8" in summer, and 5 ins. less in fresh water has now been correctly marked on.*

*Chas. H. Jordan*

PRESENT CONDITION OF THE		Plank (Bottom) & Counter		Ceiling		Boats	
Decks		Treenails or Rivets		Rudder		Masts, Yards, &c.	
Waterways		Breasthooks and Stemson		Windlass & Capstan		Condition, how ascertained	
Comings		Transoms, Pointers, & Crutches		Pumps		Sails	
Up'r Dk. Beams & Fastenings		Timbers of Frame at the openings		Cement (if Iron Ship)		Anchors No. of	
Low'r Dk. Beams & Fastenings		Ditto ditto at other places		Caulking of Bot'm, D'k, & Watrways		Cables	
Planksheers		Keelsons		Copper, or Y.M. (State if on Felt.) When put on		Hawsers & Warps	
Sheerstrakes		Clamps & Shelves				Standing & Running Rigging	
Topsides							
Wales							
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers		Cargo & Main Hatchways	
						Hatches	

General Observations, Opinion as to Class, &c. :

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	} received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

*Warrant of Freeboard*

Committee's Minute  
Character assigned Freeboard  
FRIDAY 2 APRIL 1886  
Surveyor to Lloyd's Register of British & Foreign Shipping.

Form No. 2 for Repairs—5000—19/12/85—Transfer Ink. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.