

Report of Survey for Repairs, &c., of Engines & Boilers.

No. \_\_\_\_\_

No. in Reg. Book. *61*

Survey held at *London*

Date, first Survey *13 May*

Last Survey *1886*

on the Machinery of the *S. S. Acacia*

(Number of Visits *1*)

Tonnage, Gross *428*

Built at *Port Glasgow*

When built *1879 2*

Ditto, Net *270*

Owners *J. T. Harrison*

Port belonging to *Penzance*

Diameter of Cylinder *22 1/2*

Engines made by *Dunsmuir & Jackson*

When made *1879*

Length of Stroke *30*

Boilers made by \_\_\_\_\_

When made \_\_\_\_\_

Pressure of Steam *2*

If Surveyed Afloat or in Dry Dock *Union Dock*

Classed *A1 + 1*

Registered Horse Power *80*

(State name of Dock.)

Character in Register Book. *286*

Last Survey No. \_\_\_\_\_

Port *None*

Particulars of Repairs and Examination *Damage to vessel only*  
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

*Examined Sea cocks & connections & found them good. The tail shaft was found to have worn down 1/4"*

General Observations, Opinion, and Recommendation :— *The machinery of this vessel is not classed.*  
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27)	£	:	:	received by me, } 188
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (per Section 28)	£	:	:	
Certificate (if required)	£	:	:	
Traveling Expenses (if chargeable)	£	:	:	

Committee's Minute *Friday, 4th June, 1886.*

Assigned \_\_\_\_\_

*C. E. Bromley*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.