

Report of Survey for Repairs, &c., of Engines & Boilers.

46260

(Received at London Office, Wednesday, 16th June, 1886)

No. in Survey held at London Date, first Survey 22 May Last Survey 26 May 1886
 Reg. Book. 599 on the Machinery of the S. S. Gracie (Number of Visits 3)
 Year Month
 Tonnage, Gross 1394 Built at Hartlepool When built 1879 9
 Ditto, Net 894 Owners S. Clarke & Co Port belonging to London
 Year
 Diameter of Cylinder 36 1/2 68 Engines made by Blair & Co When made 1879
 Year
 Length of Stroke 42 Boilers made by (c) When made 1879
 Character in Register Book.
 Pressure of Steam 80 If Surveyed Afloat or in Dry Dock Carders Dry Dock Classed 100 A 1
 (State Name of Dock.) 9.55
 Registered Horse Power 180
 Last Survey No. Port L.M.C. 2.84.

Particulars of Repairs and Examination Annual Boiler Survey
 (State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Seacocks & connections found them good.
Examined the two main boilers and found them in a good condition
The bottom of the central combustion chamber (2 furnaces) has been doubled and new stays have been fitted.
The tubes have been expanded.

General Observations, Opinion, and Recommendation:-- As far as seen the
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 5. Th recorded in the Register Book

Office or Registration Fee (per Sec. 27)	£	:	:
Survey Fee (per Section 28)	£	2	2 -
Special Damage Fee (per Section 28)	£	:	:
*Certificate (if required)	£	-	5 -
Travelling Expenses (if chargeable)	£	:	:

received by me, 24/6 1886 } B.S.

C. E. Bromeyer
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRIDAY 18 JUNE 1886
 Assigned B.S. 5. Th



Form No. 9 - Transfer Ink - 2000, 8/1/86. * Certificate to be sent to the Registrar of Shipping in the Register Book. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

LOND 77-0444

It is submitted that this vessel
is eligible to have the notification
B S 5.86 recorded the boilers
being subject to resurvey as
per Rule.

DP
16/6/86.

[Faint, illegible handwritten notes in the left margin, possibly bleed-through from the reverse side.]

[Faint, illegible handwritten notes in the center margin, possibly bleed-through from the reverse side.]



© 2021
Lloyd's Register
Foundation