

REPORT of SURVEY for REPAIRS, &c.

Received in London Office.

FRIDAY 20 AUGUST 1886

No. 46459

No. in Reg. Book.

Survey held at

London

Date, First Survey

12 Augr

Last Survey

13<sup>th</sup> Augr

1886

on the

BK Dartmouth

Master

Hy Collins

TONNAGE:-

Built at

Bundee

By whom

A Stephen & Son

When

1859

NET 915

GROSS 978

UNDER DK. 839

Ownes

George Brownell

Port belonging to

London, England

Owners' Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Name of Dock

Regents Dry Dock

Destined Voyage

Tyng & West Coast of America to trade there

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

6<sup>th</sup> 5.85.

Cent in June 76, 11 yrs

H.T. Son 82.

Last Survey, No.

44980

Port

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned) in salt water ft. ins. as painted on Ship in fresh water ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in the dry dock, and the examined. Rudder bottom repaired, and the yellow metal patched and mended.

Robert Webb & Co

11 Great Saint Helens

Will pay the fees

PRESENT CONDITION OF THE

Decks	Good	Plank (Bottom) & Counter	Good	Celling	Good	Boats	Good
Waterways	"	Treenails on Decks	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	Good
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of	3 Iron St & 2 Ho
Planksheers	"	Ditto ditto at other places	"	Caulking of Bottom, D'k, & Watrways	"	Cables	Part on St & Ho
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. Metal	"	Hawsers & Warps	"
Topsides	"	Clamps & Shells	"	When put on	"	Standing & Running Rigging	"
Wales	"		"		"	Hatches	"
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers	Good	Cargo & Main Hatchways	Good

General Observations, Opinion as to Class, &c.:

She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

Entry Fee (if chargeable) per Sec. 27. £  
Office Fee (if chargeable) per Sec. 27. £  
Survey Fee (per Section 28) £  
Special Damage Fee (if any) per Sec. 28) £  
Certificate (if required) to be sent as per margin £  
Travelling Expenses (if chargeable) £  
Second Surveyor's Fee (if any) £

received by me, HCU  
20 Aug 1886

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

TUESDAY 24 AUGUST 1886