

# REPORT of SURVEY for REPAIRS, &c.

TUESDAY 21 SEPT 1886

Received in London Office,

No. 46547

No. in Reg. Book.

Survey held at London

Date, First Survey 19<sup>th</sup> August - Last Survey 14<sup>th</sup> Sept 1886

753 on the Composite Ship "Solraon".

Master Elmslie.

TONNAGE:—

Built at Aberdeen By whom Hall

When 1866

NET 2131

Owners Dewitt & Moore

Port belonging to London.

GROSS 2131

UNDER DEK. 2089

Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Day

Name of Dock West India Destined Voyage Melbourne

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

A1 17<sup>th</sup> Dec 83.

Last Survey, No. 45369 Port London

Cont. Lon. Dec 83. 11<sup>th</sup> Dec 83.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in salt water ft. ins. in fresh water ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE

Condition, Remetaling,

The metal has been stripped off, and the bottom caulked and remetaled over felt.

Examined the inside of the vessel and found a diagonal tie plate fractured, (on the port side aft.) A strong plate has been fitted on the inside of the frames in way of the fracture as compensation.

PRESENT CONDITION OF THE

Decks

Good

Waterways

"

Comings

"

Up'r Dk. Beams & Fastenings

"

Low'r Dk. Beams & Fastenings

"

Planksheers

"

Sheerstrakes

"

Topsides

"

Wales

"

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Ceiling

Good

Rudder

"

Windlass & Capstan

"

Pumps

"

Cement (if Iron Ship)

"

Caulking of Bot'm, D'k, & Wat'rways

"

Copper, or Yellow Metal, on felt (State if on felt.)

When put on August 1886

Scuppers

Good

Cargo & Main Hatchways

Boats

Good

Masts, Yards, &c.

"

Condition, how ascertained

from deck

Sails

"

Anchor

No. of 3 B. 15. 2k

Cables

part seen good

Hawsers & Warps

Suitable

Standing & Running Rigging

Good

Hatches

"

General Observations, Opinion as to Class, &c.:

This vessel now appears to be in a sound and efficient condition, eligible in our opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27.

Office Fee (if chargeable) per Scale II., Sec. 27.

Survey Fee (per Section 28)

Special Damage Fee (if any) (per Sec. 28)

\*Certificate (if required) to be sent as per margin

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

£ — — —

£ — — —

£ 2 2 —

£ — — —

£ — 5 —

£ — — —

£ — — —

received by me 25/9/1886

Allison B. Wilson.

Mr. C. Dancy

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 21 SEPT 1886

Committee's Minute

Character assigned