

REPORT of SURVEY for REPAIRS, &c.

WEDNES. 8 OCT 1886

No.

No. in Reg. Book.

Survey held at

London

Date, First Survey 15 Sept

Last Survey 29 Sept 1886

421 on the

S Torrens (Compton)

Master H Angel

YEAR.

MONTH.

TONNAGE:—

NET 1276

GROSS 1335

UNDER DECK 658

Built at Sunderland

By whom J Lang

When 1875

10

Owners A L Elder

Port belonging to London

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Name of Dock Linthouse Dry Dock Destined Voyage Australia

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed 18 A 10, 85
58 Lin 84

Last Survey, No. 45432 Port Lon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship)

in salt water

ft.

ins.

in fresh water

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in the Dry Dock the Yellow Metal stripped off and bottom examined. Caulked from keel to about load line and Reyellow Metalled to same height on bare plank.

PRESENT CONDITION OF THE

Decks

Good

Plank (Bottom) & Counter

Good

Ceiling

Good

Boats

Good

Waterways

Good

Treenails or Rivets

Good

Rudder

Good

Masts, Yards, &c.

Good

Comings

Good

Breasthooks and Stemson

Good

Windlass & Capstan

Good

Condition, how ascertained Gun 8th

Up'r Dk. Beams & Fastenings

Good

Transoms, Pointers, & Crutches

Good

Pumps

Good

Sails

Good

Low'r Dk. Beams & Fastenings

Good

Timbers of Frame at the openings

Good

Cement (if Iron Ship)

Good

Anchors No. of 8 lbs. 12 & 2 lbs.

Planksheers

Good

Ditto ditto at other places

Good

Caulking of Bot'm, D'k, & Wat'rways

Good

Cables Part on 8th

Sheerstrakes

Good

Keelsons

Good

Support of Y.M. of Metal to load line

Good

Hawsers & Warps

Good

Topsides

Good

Clamps & Shelves

Good

When put on 9.86

Good

Standing & Running Rigging

Good

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo & Main Hatchways

Good

Hatches

Good

General Observations, Opinion as to Class, &c.:

She is now in an efficient state and eligible to remain as classed.

Leithhouse Martin

Entry Fee (if chargeable) per Scale I., Sec. 27.

£

Office Fee (if chargeable) per Scale II., Sec. 27.

£

Survey Fee (per Section 28)

£

Special Damage Fee (if any) (per Sec. 28)

£

*Certificate (if required) to be sent as per margin

£

Travelling Expenses (if chargeable)

£

Second Surveyor's Fee (if any)

£

received by me

12.10 1886

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 8 OCT 1886

Character assigned

18

Tenants

1. Name of Tenant
2. Address
3. Date of Survey
4. Name of Surveyor

5. Description of Property
6. Description of Defects
7. Estimated Cost of Repairs

8. Remarks
9. Signature of Surveyor
10. Date of Report

11. Name of Landlord
12. Address
13. Date of Survey
14. Name of Surveyor

15. Description of Property
16. Description of Defects
17. Estimated Cost of Repairs

18. Remarks
19. Signature of Surveyor
20. Date of Report

21. Name of Landlord
22. Address
23. Date of Survey
24. Name of Surveyor

25. Description of Property
26. Description of Defects
27. Estimated Cost of Repairs

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN