

REPORT of SURVEY for REPAIRS, &C.

46601

Received in London Office,

SAT 9 OCT 1886

No. 46601

No. in Reg. Book. 26 Survey held at London Date, First Survey 17 Septe Last Survey 7th Octr 1886
 on the S Waimate (No. of Visits) Master H. A. Tribe

TONNAGE:— NET 1123 GROSS 1156 UNDER DECK 106
 Built at Sunderland By whom J Blumer & Co When 1874 8.
 Owners New Zealand S Co Port belonging to Lyttelton
 Owner's Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Name of Dock Destined Voyage New Zealand
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Classed 100 A 12.85
 Character in Register Book S.S. Line 01283

Last Survey, No. 45604 Port Lon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 in salt water ft. ins.
 as painted on Ship (if assigned) in fresh water ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in the dry dock the bottom cleaned examined and coated.

PRESENT CONDITION OF THE

Decks	good	Plank (Bottom) & Counter	good	Ceiling	good	Boats	good
Waterways	"	Freeboards or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	From Deck
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of 3 lbs, 4 & 2 lbs	
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'K, & Watrways	"	Cables Part on Deck	good
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Deck.)	"	Hawsers & Warps	"
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	good	Cargo & Main Hatchways	good

General Observations, Opinion as to Class, &c.:

She is now in an efficient state and eligible to remain as classed.


Leahouse Martindale

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	received by me, } 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
 Character assigned 100 A 1

TUESDAY 12 OCT 1886



Lloyd's Register Foundation

Form No. 2 for Repairs—5000—20/9/85—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

LON 678-0341

Hammali



© 2021
Lloyd's Register
Foundation