

REPORT of SURVEY for REPAIRS, &c. 46603

Received in London Office,

MONDAY 6 SEPT 1886

No. in Reg. Book. *289* Survey held at *London* Date, First Survey *4th Sept* Last Survey *4th Sept* 188*6*
 on the *SS Richmond* Master *J Meyer*
 (No. of Visits) (YEAR) MONTH.

TONNAGE:—
 NET *769* Built at *Newcastle* By whom *Schlesinger* When *1871* /
 GROSS *1234* Owners *Watt Ward & Co* Port belonging to *London*
 UNDER DK. *994* Owners' Address
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Name of Dock *W J J Dock* Destined Voyage *Newport*

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)
 Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. *Fourth Survey Jan 85* Port *London*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water ft. ins.
 account of Damage should be separated from Repairs due to other causes. State also the dates and Initials) as painted on Ship. in fresh water ft. ins.
 matters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE
*The order to survey this vessel was entered in the order book yesterday (3rd inst) and on visiting her this morning the Captain and his officers were on shore, and stated by a labourer on board to be at the shipping office shipping a crew to proceed to Lond there (Newport)
 A double gang of hands were getting the side bunkers with coals, the part recommended to be surveyed by attached Memorandum from our London office.*

Senhouse Martindale

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Plank-sheets	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Fell.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c. :

Entry Fee (if chargeable) per Scale I, Sec. 27.	£	:	:
Office Fee (if chargeable) per Scale II, Sec. 27.	£	:	:
Survey Fee (per Section 28)	£	:	:
Special Damage Fee (if any) (per Sec. 28)	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:


received by me, *188*

See the 28th Sept 1886

Committee's Minute
 Character assigned
Schlesinger 9/9/86

TUESDAY 28 SEPT 1886

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

46603-034