

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,)

No. 406 Port of London
 No. in Reg. Book. 406 Survey held at London Date, first Survey Sept. 27 Last Survey 12 Nov 1886
 on the Machinery of the S.S. "Glencoe" (Number of Visits 6)
 Tonnage, Gross 2913 Built at Glasgow When built 1878-11
 Ditto, Net 1901 Owners McGregor Low & Co. Port belonging to Glasgow
 Diameter of Cylinder 48" x 38" Engines made by Lon. & Glas. Co. When made 1878
 Length of Stroke 60" Boilers made by Do. When made 1878
 Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock Greens & Aft. Classed 100A1
 Registered Horse Power 550 (State Name of Dock.)
 Last Survey No. 1.M.C 1. 83 B.S. 4. 85. Port 100A1

Particulars of Repairs and Examination For Annual Survey

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in Dry dock, sea connections examined and found to be in good condition, the propeller & its connections sound & the tail shaft down $\frac{3}{16}$ in Stern bush.

Examined 2 main boilers (double ended through combustion chambers) and the horizontal superheater & found them in a good condition.

The safety valves were found to blow off at 75 lbs.
 The donkey boiler has not been open submitted for survey.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 1186 recorded in the Register Book.

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ 2 : 2
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me, 16-3-1887

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

FRIDAY 10 DEC 1886

Assigned

B.S. 1186

Return to Mr. Steel

© 2021

Lloyd's Register Foundation

LON619-0030

It is submitted that this vessel
is eligible to have the notification
B.S. 11.86 recorded subject to
the survey of donkey
boiler on the vessels
return

DP
6/12/86

