

REPORT of SURVEY for REPAIRS, &c.

46865  
THURS 23 DEC 1888

No. 46865 Port of London  
No. in Survey held at Date, First Survey 16<sup>th</sup> Dec Last Survey 17<sup>th</sup> Dec 1888  
g. Book. on the SS El Dorado Master Sampson  
134

TONNAGE:—  
NET 864  
GROSS 1343  
UNDER DE 1111  
Built at N Shields By whom J & W Smith When 882  
Owners El Dorado SS Co Scrutton Sons & Co Port belonging to London  
Owner's Address  
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Name of Dock Union Dry Dock Destined Voyage West Indies  
Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.  
(if these particulars are not yet recorded in the Register Book.)  
Classed 100 A-2.86

Last Survey, No. 45977 Port Lon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.  
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter ft. ins.  
of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

at present placed in the dry dock  
and the bottom cleaned examined & coated.  
Rudder Bushed.

PRESENT CONDITION OF THE

Decks	Good	Plank (Bottom) & Counter	Good	Celling	Good	Boats	Good
Waterways	1	Trunnels or Rivets	1	Rudder Bushed	1	Masts, Yards, &c.	1
Comings	1	Breasthooks and Stemson	1	Windlass & Capstan	1	Condition, how ascertained	From Stk
Up'r Dk. Beams & Fastenings	1	Transoms, Pointers, & Crutches	1	Pumps	1	Sails	Good
Low'r Dk. Beams & Fastenings	1	Timbers of Frame at the openings	1	Cement (if Iron Ship)	1	Anchor No. of 3 No. 12 1/2 lb	1
Planksheers	1	Ditto ditto at other places	1	Caulk'g of Bot'm, D'k, & Watrways	1	Cables Part on Stk	Good
Sheerstrakes	1	Keelsons	1	Copper or T.M.	1	Hawsers & Warps	1
Topsides	1	Clamps & Shelves	1	(State if on Petrol)	1	Standing & Running Rigging	1
Wales	1			When put on	1	Hatches	1
Engine Room Skylights	Good	Coal Bunker, Openings, Lids, &c.	Good	Scuppers	Good	Cargo & Main Hatchways	1

General Observations, Opinion as to Class, Recommendation, &c.:

She is now in an efficient state  
and eligible to remain as classed,  
The overboarder stated that SS No 1 would be done next voyage

Entry Fee (if chargeable) per Scale I., Sec. 27...	£			
Office Fee (if chargeable) per Scale II., Sec. 27...	£			
Survey Fee (per Section 28) .....	£			
Special on Damage, Fee (if any) (per Sec. 28)....	£			
*Certificate (if required) to be sent as per margin	£			
Travelling Expenses (if chargeable) .....	£			
Second Surveyor's Fee (if any) .....	£			

Fees  
received by me,  
188

Committee's Minute  
Character assigned

FRIDAY 7 JAN 1887

100 A-2.86

Serhouse Martindale  
Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation



N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

El. Smith

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021

Lloyd's Register  
Foundation