

REPORT of SURVEY for REPAIRS, &c.

46866

46866

Received in London Office, **TUESDAY 4 JAN 1887**

Port of London

Survey held at London

Date, First Survey 18th Dec^r Last Survey Dec 3 1886

438 on the Iron Ship "Duke of Connaught" (late City of Madras) Master Falconer.

TONNAGE:—
NET 999
GROSS 1034
UNDER DK. 954

Built at Glasgow.
By whom A. Stephen & Sons.
Owners Montgomerie & Workman
Owner's Address
(if not already recorded in Appendix to Register Book.)

When 1859
Port belonging to London.

If Surveyed Aft or in Dry Dock & Dry Dock Name of Dock Poplar.

Destined Voyage Maryport thence to Australia

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.)

Classed _____
Character in Register Book *A.1
11,85.

Last Survey, No. 4208 Port GLS

S.S. Bly. N^o 3-80, S.S. Lir. N^o 1-85.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR

The bottom has been examined and coated. One rudder brace renewed. This vessel has started for Maryport and the following are by Owner's desire intended to be done, viz: a patent windlass to be fitted. Another boat to be supplied - at present there are three boats on board - there were four boats, the towline now on board to be replaced by a 3 1/2 inch wire hawser with manilla spring; a 2" wire hawser to be supplied.

PRESENT CONDITION OF THE

| | | | |
|------------------------------|----------------------------------|---|----------------------------|
| Decks | Plank (Bottom) & Counter | Ceiling | Boats |
| Waterways | Treenails or Rivets | Rudder | Masts, Yards, &c. |
| Comings | Breasthooks and Stemson | Windlass & Capstan | Condition, how ascertained |
| Up'r Dk. Beams & Fastenings | Transoms, Pointers, & Crutches | Pumps | Sails |
| Low'r Dk. Beams & Fastenings | Timbers of Frame at the openings | Cement (if Iron Ship) | Anchors No. of |
| Planksheers | Ditto ditto at other places | Caulk'ng of Bot'm, D'k, & Watrways | Cables |
| Sheerstrakes | Keelsons | Copper, or Y.M. (State if on Felt.) When put on | Hawsers & Warps |
| Topsides | Clamps & Shelves | | Standing & Running Rigging |
| Wales | | | |
| Engine Room Skylights | Coal Bunker, Openings, Lids, &c. | Scuppers | Cargo & Main Hatchways |
| | | | Hatches |

General Observations, Opinion as to Class, Recommendation, &c.:

So far as seen, this vessel appeared to be in good condition & eligible to remain as classed.

| | | | | |
|--|---|---|---|--------------------------------|
| Entry Fee (if chargeable) per Scale I., Sec. 27... | £ | : | : | Fees received by me, 188 |
| Office Fee (if chargeable) per Scale II., Sec. 27... | £ | : | : | |
| Survey Fee (per Section 28) | £ | 0 | 0 | |
| Special on Damage, Fee (if any) (per Sec. 28).... | £ | : | : | |
| *Certificate (if required) to be sent as per margin | £ | : | : | |
| Travelling Expenses (if chargeable) | £ | : | : | |
| Second Surveyor's Fee (if any) | £ | : | : | |

J. H. Truscott.
Surveyor to Lloyd's Register of British & Foreign Shipping.



Committee's Minute FRIDAY 7 JAN 1887
Character assigned *A.1